

HAZARDOUS MATERIALS SURVEY AND 2023 REASSESSMENT 200 LEES AVENUE, OTTAWA, ONTARIO



Project No.: Z1920014HZ / CCC-230252-00

Prepared for:

University of Ottawa

Prepared by:

McIntosh Perry Limited (MPL)

MPL Contact:

John Tufts, Project Manager

Hazardous Materials / Environmental Health & Safety

T: 613-836-2184 E: j.tufts@mcintoshperry.com

Date:

March 8, 2024

McINTOSH PERRY

TABLE OF CONTENTS

| | |
|---|----------|
| REASSESSMENT SURVEY 2023 | I |
| EXECUTIVE SUMMARY | I |
| 1.0 INTRODUCTION | 1 |
| 2.0 PROPERTY DESCRIPTION | 2 |
| 3.0 FINDINGS & RECOMMENDATIONS | 2 |
| <i>Designated Substances</i> | 2 |
| 3.1 <i>Asbestos</i> | 2 |
| 3.1.1 Fireproofing | 8 |
| 3.1.2 Mechanical Pipe Insulation | 8 |
| 3.1.3 Flexible Duct Connector | 9 |
| 3.1.4 Heat Shield or Heat Shield Insulation | 9 |
| 3.1.5 Texture Finishes | 9 |
| 3.1.6 Plaster | 9 |
| 3.1.7 Drywall Joint Compound | 10 |
| 3.1.8 Ceiling Tiles | 10 |
| 3.1.9 Vinyl Floor Tiles | 10 |
| 3.1.10 Levelling Compound | 11 |
| 3.1.11 Concrete Block Mortar | 11 |
| 3.1.12 Ceramic Wall / Floor Tile Grout | 12 |
| 3.1.13 Transite (Asbestos Cement) | 12 |
| 3.1.14 Caulking | 12 |
| 3.1.15 Cementitious Coating | 12 |
| 3.1.16 Mastic | 12 |
| 3.1.17 Tar | 12 |
| 3.1.18 Fire Door | 12 |
| 3.1.19 Roofing Material | 12 |
| 3.2 <i>Lead</i> | 14 |
| 3.2.1 Paint Finishes | 14 |

| | | |
|--|---|----|
| 3.2.2 | Battery Packs | 15 |
| 3.2.3 | Lead Shielding | 15 |
| 3.3 | <i>Mercury</i> | 16 |
| 3.3.1 | Thermostat Switches..... | 16 |
| 3.3.2 | Fluorescent Light Tubes | 17 |
| 3.3.3 | Pressure Gauges and Float Switches..... | 17 |
| 3.4 | <i>Silica</i> | 17 |
| 3.5 | <i>Polychlorinated Biphenyls (PCBs)</i> | 18 |
| 3.5.1 | Light Ballasts | 18 |
| 3.5.2 | Transformers | 18 |
| 3.6 | <i>Ozone Depleting Substances (ODSs) and Other Halocarbon</i> | 18 |
| 3.7 | <i>Radioactive Materials</i> | 19 |
| 3.8 | <i>Underground and Above Ground Storage Tanks (USTs and ASTs)</i> | 19 |
| 3.9 | <i>Mould</i> | 19 |
| 3.9.1 | Mould | 19 |
| 3.9.2 | Water Damage..... | 20 |
| 4.0 | GENERAL CONSIDERATIONS AND LIMITATIONS | 21 |
| | | |
| Appendix A – Regulatory Requirements | | |
| Appendix B – Survey Methodology & Background Information | | |
| Appendix C – Laboratory Certificate of Analysis | | |
| Appendix D– Site Photographs | | |
| Appendix E – Asbestos Containing Materials Checklist | | |
| Appendix F – Hazardous Containing Materials Checklist | | |
| Appendix G – Site Sampling & Location Plans | | |

REASSESSMENT SURVEY 2023

McIntosh Perry Limited (**MPL**) was retained by the University of Ottawa, to complete to a hazardous materials survey of Marchand Residence located at 200 Lees Avenue, in Ottawa, Ontario. The original survey was conducted between September 30th to October 3rd, 2019. **The reassessment was completed on August 25th, 2023.**

The purpose of the reassessment was to evaluate the condition and quantity of previously reported asbestos-containing materials (ACM) and develop corrective action plans as required for the purposes of long-term management.

The assessment and reassessment determined the following findings and recommendations.

Summary of the Reassessment Findings:

- ACM Plaster was observed to be in Good Condition in various locations throughout the subject building.
- ACM Vinyl Floor Tiles was observed to be in Good Condition in Room C144 and C110.
- ACM Interior Window Caulking was observed to be in Good Condition in Room A139.
- ACM Parging Cement Insulation was observed to be in Good Condition in Room A104C and E029
- ACM Pipe Straight Insulation was observed in Good Condition in Room A105.
- No mould affected or water damaged materials were observed during the site survey.

Summary of Recommendations:

- Perform a reassessment of asbestos materials on an annual basis.
- Perform a pre-construction assessment and remove all asbestos-containing materials (ACM) prior to alterations or maintenance work if ACM may be disturbed by the work.
- Follow appropriate safe work procedures when handling or disturbing asbestos.

Sample any presumed ACM prior to alteration or maintained work if presumed ACM may be disturbed by the work.

EXECUTIVE SUMMARY

McIntosh Perry Limited (**MPL**) was retained by the University of Ottawa, to complete a hazardous materials survey for the University building located at 200 Lees Avenue, in Ottawa, Ontario. The original survey was conducted between September 30th to October 3rd, 2019. **The reassessment was completed on August 25th, 2023.**

The purpose of the survey was to determine the presence of building materials containing Designated Substances and other hazardous materials, as defined under the Ontario Occupational Health and Safety Act. Designated Substances are eleven chemical agents prescribed under Ontario Regulation 490/09. In addition, a visual assessment was conducted for the presence of polychlorinated biphenyls (PCBs), radioactive materials, ozone depleting substances (ODSs), other halocarbons and mould.

Based on the assessment conducted by MPL, the following ACMs were previously identified or suspected to be present in the building:

Table A: Summary of Asbestos-Containing Materials Identified

| Material Description | Friable? | Location | Type of Asbestos |
|----------------------------|----------|---------------------|------------------|
| Mechanical Pipe Insulation | Yes | Specific Areas Only | Chrysotile |
| Plaster | Yes | Specific Areas Only | Tremolite |
| Gaskets | No | Specific Areas Only | Chrysotile |
| Interior Window Caulking | No | Specific Areas Only | Chrysotile |
| Vinyl Floor Tiles | No | Specific Areas Only | Chrysotile |
| Transite | No | Specific Areas Only | Suspected |
| Fire doors | - | Throughout Building | Suspected |
| Roofing Materials | - | Building Exterior | Suspected |

Note: Please refer to the complete report for specific details and recommendations.

All repairs or removal of asbestos-containing materials must be conducted according to Ontario Regulation 278/05, Regulation respecting Asbestos on Construction Projects and in Buildings and Repair Operations - made under the Occupational Health and Safety Act. Asbestos containing waste must also be handled and disposed of according to Ontario Regulation 347/90 as amended – made under the Environmental Protection Act. Any suspect building materials encountered that were not assessed as part of this survey, should be assumed to contain asbestos until proven otherwise by analytical testing;

Sub-trades working with or in close proximity asbestos-containing material should be informed of its presence;

Given that asbestos containing materials (ACMs) have been identified and will likely remain in place, an Asbestos Management Plan (AMP) is therefore required and an inventory of ACMs must be kept on site. All ACMs must be routinely inspected to ensure no damage has occurred, and the inventory must be updated once

in each 12-month period and as may be required based on expected changing site conditions, abatement and/or renovation activities.

Based on the assessment conducted by MPL, the following Designated Substances and Hazardous Materials were previously identified or suspected to be present in the building:

Table B: Summary of Designated Substances & Hazardous Materials Identified

| Material Description | Location |
|-----------------------------|---------------------|
| Lead Paint | Specific Areas Only |
| Lead Acid Batteries | Throughout Building |
| Mercury Vapour | Throughout Building |
| Ozone Depleted Substances | Specific Areas Only |
| Radioactive Materials | Specific Areas Only |
| Mould | Specific Areas Only |

Note: Please refer to the complete report for specific details and recommendations.

Designated Substances area regulated under Ontario Regulation 490/09 — Designated Substances, made under the Ontario Health and Safety Act, which applies to controlling designated substances in the workplace.

In addition to Ontario Regulation 490/09, the following guidelines must also be adhered to when conducting work activities that involve disturbance of the above-mentioned materials:

- Guideline: Lead on Construction Projects, issued April 2011 by the Occupational Health and Safety branch of the Ministry of Labour
- Guideline: Silica on Construction Projects issued April 2011 by the Occupational Health and Safety branch of the Ministry of Labour.
- Environmental Abatement Council of Ontario (EACO) Mould Abatement Guidelines.

Prior to any renovations or demolition activities within building, designated substances and hazardous materials must be decommissioned by a licensed contractor such that they are contained and not released to the environment during decommissioning as per O. Reg. 347/09- made under the Environmental Protection Act.

Any suspect building materials encountered that were not assessed as part of this survey, should be assumed to contain designated substances or hazardous materials until proven otherwise by analytical testing.

This report should be made available to contractors tendering on any renovation or demolition work. In turn, all contractors requesting tenders from subcontractors shall furnish this report to subcontractors.

This executive summary is not to be used alone. This report should be reviewed in its entirety.

March 8, 2024

University of Ottawa
141 Louis-Pasteur Private
Ottawa, Ontario
K1N 1E3

via email: martine.bergeron@uottawa.ca

Attention: Martine Bergeron, Senior Specialist, Occupational Health and Safety

Re: 200 Lees Avenue, in Ottawa, Ontario
Hazardous Materials Survey and 2023 Reassessment
McIntosh Perry Limited Reference No. Z1920014HZ / CCC-230252-00

1.0 INTRODUCTION

In accordance with your instructions, McIntosh Perry Limited (MPL) carried out a Hazardous Materials Survey and 2023 Reassessment at the university building located at 200 Lees Avenue, in Ottawa, Ontario. The survey of the building was conducted on September 30th to October 2nd, 2019.

The purpose of the survey was to determine the presence of building materials containing Designated Substances and other hazardous materials, as defined under the Ontario Occupational Health and Safety Act. Designated Substances are eleven chemical agents prescribed under Ontario Regulation 490/09. In addition, a visual assessment was conducted for the presence of polychlorinated biphenyls (PCBs), radioactive materials, ozone depleting substances (ODSs), other halocarbons and mould.

MPL completed the following,

- Visual review of the building to identify materials which could contain Designated Substances and hazardous materials;
- Review of previously completed Hazardous Materials Survey(s) and historical building record(s); and,
- Recommendations for appropriate action where required.

2.0 PROPERTY DESCRIPTION

The subject building is comprised of five distinct premises (A, B, C, D and E) that are interconnected and range from one to three storeys. The subject building was observed to be constructed with a concrete slab floor; metal roof supported by steel trusses, beams and columns. The interior walls were gypsum wallboard and concrete block, with select areas containing ceramic tiles. Within the subject building, ceilings were observed to be either suspended ceiling tiles, while open ceilings were observed in other areas of the building. The floors were generally concrete throughout the subject building with the exception of select units containing vinyl floor tiles, terrazzo flooring, laminate flooring and carpet. The Buildings A to D were constructed circa 1963 while Building E was constructed circa 1980.

3.0 FINDINGS & RECOMMENDATIONS

Designated Substances

3.1 Asbestos

Findings

A total of one-hundred and fifty (150) bulk samples were previously collected during the survey and sent to an accredited laboratory for analysis. A summary of potential asbestos-containing samples collected along with the sample location, type and friability are presented in Table 1.

The following subsections and tables outlines our findings of asbestos containing materials throughout the subject building. Laboratory certificates of analysis for asbestos are included in Appendix C.

Table 1:
Asbestos Sampling Laboratory Results

| Sample ID | Location | Material | Type and Content | Friability |
|-----------|-----------|---|------------------|-------------|
| BS 1.1 | Room A02 | Gasket (Beige) | 65% Chrysotile | Non-Friable |
| BS 1.2 | Room A02 | Gasket (Beige) | Stop Positive | Non-Friable |
| BS 1.3 | Room A02 | Gasket (Beige) | Stop Positive | Non-Friable |
| BS 2.1 | Room 104C | Mechanical Pipe Fitting Insulation (Grey) | 60% Chrysotile | Friable |
| BS 2.2 | Room 104C | Mechanical Pipe Fitting Insulation (Grey) | Stop Positive | Friable |
| BS 2.3 | Room 104C | Mechanical Pipe Fitting Insulation (Grey) | Stop Positive | Friable |
| BS 3.1 | Room A105 | Mechanical Pipe insulation (Brown) | 10% Chrysotile | Friable |
| BS 3.2 | Room A105 | Mechanical Pipe insulation (Brown) | Stop positive | Friable |
| BS 3.3 | Room A105 | Mechanical Pipe insulation (Brown) | Stop positive | Friable |

| Sample ID | Location | Material | Type and Content | Friability |
|---------------|------------------|--|----------------------|--------------------|
| BS 4.1 | Room A140 | Floor levelling compound (Brown/Black) | None Detected | N/A |
| BS 4.2 | Room A140 | Floor levelling compound (Brown/Black) | None Detected | N/A |
| BS 4.3 | Room A140 | Floor levelling compound (Brown/Black) | None Detected | N/A |
| BS 5.1 | Room A139 | Wall Plaster (Gray) | None Detected | N/A |
| BS 5.2 | Room A139 | Wall Plaster (Gray) | None Detected | N/A |
| BS 5.3 | Room A139 | Wall Plaster (Gray) | None Detected | N/A |
| BS 6.1 | Room A144 | High Traffic Floor Coating (Beige) | None Detected | N/A |
| BS 6.2 | Room A144 | High Traffic Floor Coating (Beige) | None Detected | N/A |
| Bs 6.3 | Room A144 | High Traffic Floor Coating (Beige) | None Detected | N/A |
| BS 7.1 | Room A139 | Window Caulking (Black) | 2% Chrysotile | Non-Friable |
| BS 7.2 | Room A139 | Window Caulking (Black) | Stop Positive | Non-Friable |
| BS 7.3 | Room A139 | Window Caulking (Black) | Stop Positive | Non-Friable |
| BS 8.1 | Room A136 | VFT(12"x12"- Off white with Gray & Black streak) | None Detected | N/A |
| BS 8.2 | Room A136 | VFT(12"x12"- Off white with Gray & Black streak) | None Detected | N/A |
| BS 8.3 | Room A136 | VFT(12"x12"- Off white with Gray & Black streak) | None Detected | N/A |
| BS 9.1 | Room A138E | VFT (12"x12"-Beige with Brown & Grey flakes) | None Detected | N/A |
| BS 9.2 | Room A138E | VFT (12"x12"-Beige with Brown & Grey flakes) | None Detected | N/A |
| BS 9.3 | Room A138E | VFT (12"x12"-Beige with Brown & Grey flakes) | None Detected | N/A |
| BS 10.1 | Room A122B | VFT (12"x12"- Olive green with Grey flakes) | None Detected | N/A |
| BS 10.2 | Room A122B | VFT (12"x12"- Olive green with Grey flakes) | None Detected | N/A |
| BS 10.3 | Room A122B | VFT (12"x12"- Olive green with Grey flakes) | None Detected | N/A |
| BS 11.1 | Room A147 | VFT (12"x12" – Grey with Blue streaks) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |
| BS 11.2 | Room A147 | VFT (12"x12" – Grey with Blue streaks) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |

| Sample ID | Location | Material | Type and Content | Friability |
|-----------|------------|--|------------------|------------|
| BS 11.3 | Room A147 | VFT (12"x12" – Grey with Blue streaks) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |
| BS 12.1 | Room A122B | VFT(12"x12"– Offwhite with Brown flakes) | None Detected | N/A |
| BS 12.2 | Room A122B | VFT(12"x12"– Offwhite with Brown flakes) | None Detected | N/A |
| BS 12.3 | Room A122B | VFT(12"x12"– Offwhite with Brown flakes) | None Detected | N/A |
| BS 13.1 | Room A142 | Concrete Block Mortar (Grey) | None Detected | N/A |
| BS 13.2 | Room A142 | Concrete Block Mortar (Grey) | None Detected | N/A |
| BS 13.3 | Room A142 | Concrete Block Mortar (Grey) | None Detected | N/A |
| BS 14.1 | Room A106C | Wall Tile Grout (Grey) | None Detected | N/A |
| Bs 14.2 | Room A106C | Wall Tile Grout (Grey) | None Detected | N/A |
| BS 14.3 | Room A106C | Wall Tile Grout (Grey) | None Detected | N/A |
| BS 15.1 | Room A139 | Wall Texture Coating (Grey) | None Detected | N/A |
| BS 15.2 | Room A139 | Wall Texture Coating (Grey) | None Detected | N/A |
| BS 15.3 | Room A139 | Wall Texture Coating (Grey) | None Detected | N/A |
| BS 15.4 | Room A139 | Wall Texture Coating (Grey) | None Detected | N/A |
| BS 15.5 | Room A139 | Wall Texture Coating (Grey) | None Detected | N/A |
| BS 15.6 | Room A139 | Wall Texture Coating (Grey) | None Detected | N/A |
| BS 15.7 | Room A139 | Wall Texture Coating (Grey) | None Detected | N/A |
| BS 16.1 | Room A36 | SCT (2'x4' - Fissures) | None Detected | N/A |
| BS 16.2 | Room A36 | SCT (2'x4' - Fissures) | None Detected | N/A |
| BS 16.3 | Room A36 | SCT (2'x4' - Fissures) | None Detected | N/A |
| BS 17.1 | Room A106 | SCT (2'x4' – Pinholes with Large Fissures) | None Detected | N/A |
| BS 17.2 | Room A106 | SCT (2'x4' – Pinholes with Large Fissures) | None Detected | N/A |
| BS 17.3 | Room A106 | SCT (2'x4' – Pinholes with Large Fissures) | None Detected | N/A |
| BS 18.1 | Room A106C | VFT (12"x12"-Red with flakes) | None Detected | N/A |
| BS 18.1 | Room A106C | Mastic | None Detected | N/A |
| BS 18.2 | Room A106C | VFT (12"x12"-Red with flakes) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |

| Sample ID | Location | Material | Type and Content | Friability |
|----------------|-------------------|---|----------------------|----------------|
| BS 18.3 | Room A106C | VFT (12"x12"-Red with flakes) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |
| BS 19.1 | Room B202B | Carpet Mastic (Brown) | None Detected | N/A |
| BS 19.2 | Room B202B | Carpet Mastic (Brown) | None Detected | N/A |
| BS 19.3 | Room B202B | Carpet Mastic (Brown) | None Detected | N/A |
| BS.20.1 | Room BS215E | VFT (2'X2' -Off white) | None Detected | N/A |
| BS.20.2 | Room BS215E | VFT (2'X2' -Off white) | None Detected | N/A |
| BS.20.3 | Room BS215E | VFT (2'X2' -Off white) | None Detected | N/A |
| BS 21.1 | Room B215N | Wall Plaster (Gray) | None Detected | N/A |
| BS 21.2 | Room B215N | Wall Plaster (Gray) | 1% Tremolite | Friable |
| BS 21.3 | Room B215N | Wall Plaster (Gray) | Stop Positive | Friable |
| BS 22.1 | Room C209 | VFT (12"X12"- Off white with Grey & Black flakes) | None Detected | N/A |
| BS 22.1 | Room C209 | Mastic (Black) | None Detected | N/A |
| Bs 22.2 | Room C209 | VFT (12"X12"- Offwhite with Grey & Black flakes) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |
| Bs 22.3 | Room C209 | VFT (12"X12"- Offwhite with Grey & Black flakes) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |
| BS 23.1 | Room C209 | VFT (12"X12"- Beige with Multicolor flakes) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |
| BS 23.2 | Room C209 | VFT (12"X12"- Beige with Multicolor flakes) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |
| BS 23.3 | Room C209 | VFT (12"X12"- Beige with Multicolor flakes) | None Detected | N/A |
| | | Mastic | None Detected | N/A |
| BS 24.1 | C200 Hallway | VFT (12"X12" – Off-white with Grey flakes) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |
| BS 24.2 | C200 Hallway | VFT (12"X12" – Offwhite with Grey flakes) | None Detected | N/A |
| BS 24.2 | C200 Hallway | Mastic (Black) | None Detected | N/A |

| Sample ID | Location | Material | Type and Content | Friability |
|-----------|--------------|--|------------------|------------|
| BS 24.3 | C200 Hallway | VFT (12"X12" – Offwhite with Grey flakes) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |
| BS 25.1 | Room C115 | VFT (12"X12" - Pink with dots) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |
| BS 25.2 | Room C115 | VFT (12"X12" - Pink with dots) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |
| BS 25.3 | Room C115 | VFT (12"X12" - Pink with dots) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |
| BS 26.1 | Room E041 | VFT (12"X12"-Offwhite with Blue streaks) | None Detected | N/A |
| | | Mastic (Yellow) | None Detected | N/A |
| BS 26.2 | Room E041 | VFT (12"X12"-Offwhite with Blue streaks) | None Detected | N/A |
| | | Mastic (Yellow) | None Detected | N/A |
| BS 26.3 | Room E041 | VFT (12"X12"-Offwhite with Blue streaks) | None Detected | N/A |
| BS 26.3 | Room E041 | Mastic (Yellow) | None Detected | N/A |
| BS 27.1 | Room E053 | VFT (12"X12"-Grey with White & Light Grey streaks) | None Detected | N/A |
| | | Mastic (Yellow) | None Detected | N/A |
| BS 27.2 | Room E053 | VFT (12"X12"-Grey with White & Light Grey streaks) | None Detected | N/A |
| | | Mastic (Yellow) | None Detected | N/A |
| BS 27.3 | Room E053 | VFT (12"X12"-Grey with White & Light Grey streaks) | None Detected | N/A |
| | | Mastic (Yellow) | None Detected | N/A |
| BS 28.1 | Room E244 | VFT (12"X12"- Offwhite with Grey streaks) | None Detected | N/A |
| | | Mastic (Yellow) | None Detected | N/A |
| BS 28.2 | Room E244 | VFT (12"X12"- Offwhite with Grey streaks) | None Detected | N/A |
| | | Mastic (Yellow) | None Detected | N/A |
| BS 28.3 | Room E244 | VFT (12"X12"- Offwhite with Grey streaks) | None Detected | N/A |

| Sample ID | Location | Material | Type and Content | Friability |
|-----------|------------|--|------------------|------------|
| | | Mastic (Yellow) | None Detected | N/A |
| BS 29.1 | Room D108 | 12"x12"- Glued on Acoustic Ceiling Tile(Uniform Holes) | None Detected | N/A |
| BS 29.2 | Room D108 | 12"x12"- Glued on Acoustic Ceiling Tile(Uniform Holes) | None Detected | N/A |
| BS 29.3 | Room D108 | 12"x12"- Glued on Acoustic Ceiling Tile(Uniform Holes) | None Detected | N/A |
| BS 30.1 | Room D108 | 12"x12"- Glued on Acoustic Ceiling Tile(Uniform Holes) | None Detected | N/A |
| | | Mastic (Brown) | None Detected | N/A |
| BS 30.2 | Room D108 | 12"x12"- Glued on Acoustic Ceiling Tile(Uniform Holes) | None Detected | N/A |
| | | Mastic (Brown) | None Detected | N/A |
| BS 30.3 | Room D108 | 12"x12"- Glued on Acoustic Ceiling Tile(Uniform Holes) | None Detected | N/A |
| | | Mastic (Brown) | None Detected | N/A |
| BS 31.1 | Room D108 | Ceiling Plaster (Grey) | None Detected | N/A |
| BS 31.2 | Room D108 | Ceiling Plaster (Grey) | None Detected | N/A |
| BS 31.3 | Room D108 | Ceiling Plaster (Grey) | None Detected | N/A |
| BS 32.1 | Room B100 | Sprayed insulation (Grey) | None Detected | N/A |
| BS 32.2 | Room C141C | Sprayed insulation (Grey) | None Detected | N/A |
| BS 32.3 | Room C141C | Sprayed insulation (Grey) | None Detected | N/A |
| BS 32.4 | Room C201 | Sprayed insulation (Grey) | None Detected | N/A |
| BS 32.5 | Room C204 | Sprayed insulation (Grey) | None Detected | N/A |
| BS 33.1 | Room A136 | Drywall Joint Compound (White) | None Detected | N/A |
| BS 33.2 | Room A139A | Drywall Joint Compound (White) | None Detected | N/A |
| BS 33.3 | Room C115 | Drywall Joint Compound (White) | None Detected | N/A |
| BS 33.4 | Room B215 | Drywall Joint Compound (White) | None Detected | N/A |
| BS 33.5 | Room C200 | Drywall Joint Compound (White) | None Detected | N/A |
| BS 33.6 | Room E146 | Drywall Joint Compound (White) | None Detected | N/A |
| BS 33.7 | Room E053 | Drywall Joint Compound (White) | None Detected | N/A |
| BS 34.1 | Room E038 | Drywall Joint Compound (White) | None Detected | N/A |
| BS 34.2 | Room E038 | Drywall Joint Compound (White) | None Detected | N/A |
| BS 34.3 | Room E038 | Drywall Joint Compound (White) | None Detected | N/A |

| Sample ID | Location | Material | Type and Content | Friability |
|-----------|-----------|-------------------------------------|------------------|------------|
| BS 35.1 | Room C115 | VFT (12"x12" - Offwhite with dots) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |
| BS 35.2 | Room C115 | VFT (12"x12" - Off white with dots) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |
| BS 35.3 | Room C115 | VFT (12"x12" - Off white with dots) | None Detected | N/A |
| | | Mastic (Black) | None Detected | N/A |

N/A – Not Applicable

VFT – Vinyl Floor Tiles

SCT-Suspended Ceiling Tiles

Stop Positive – Material considered being asbestos-containing as per O. Reg. 278/05.

Please refer to Appendix E – Asbestos-Containing Materials Checklist for material conditions, quantities (where applicable), and recommended actions. The following building materials (if present) were investigated for asbestos content:

3.1.1 Fireproofing

Sprayed fireproofing material (Grey) was observed on structural beams and walls within Rooms B100, C141C, and C201. The laboratory analytical results for the samples collected indicate that this material does not contain asbestos.

Fireproofing material was previously observed and sampled from the D-Block crawlspace. The laboratory analytical results for the samples collected indicate that this material does not contain asbestos.

3.1.2 Mechanical Pipe Insulation

3.1.2.1 Mechanical Pipe Straight Insulation

Mechanical pipe straight insulation was observed in between the workbenches in Room A105. The laboratory analytical results collected indicate that this material contains **10% Chrysotile asbestos**. This material is considered friable and was observed to be in poor condition.

3.1.2.2 Mechanical Piping Elbows/Fittings Insulation

Mechanical piping elbows/fitting insulation was observed on mechanical pipe fittings in Room A104C and E029. The laboratory analytical results of samples previously collected indicate that this material **contains 60% Chrysotile asbestos**. This material is considered friable and was observed to be in good condition, with the exception of select areas which were observed in poor condition.

Mechanical piping elbows/fitting insulation was previously observed and sampled from the E-Block Penthouse. The laboratory analytical results for the samples collected indicate that this material does not contain asbestos.

3.1.2.3 Mechanical Piping Hangers Insulation

Mechanical pipe hanger insulation was observed in the in A Block Hallways and was visually identified to be a material not suspected to contain asbestos (i.e. fibreglass) and thus not sampled.

3.1.2.4 HVAC Duct Insulation

HVAC duct insulation observed within the mechanical rooms A02, B151, B205, D201 and E301 within subject building and was visually identified to be a material not suspected to contain asbestos (i.e. fibreglass) and thus not sampled.

3.1.2.5 Other Mechanical Insulation

Mechanical pipe gasket (Beige) was observed in Room A02. The laboratory analysis indicated that this material **contains 65% Chrysotile asbestos**. This material is considered to be friable and was observed to be in poor condition.

3.1.3 Flexible Duct Connector

Suspected asbestos-containing flexible duct connector was observed on an air handling unit in Mechanical Room D201. To avoid possible damage, no bulk samples of the duct connectors were collected. However, this material is known to contain asbestos. This material is considered to be non-friable and was observed in good condition.

Flexible duct connectors were also observed in various mechanical rooms throughout the subject building. This material was visually identified as a non-asbestos containing material (i.e. rubber).

3.1.4 Heat Shield or Heat Shield Insulation

No heat shield insulation was observed in the subject building.

3.1.5 Texture Finishes

Wall texture coating was observed in Room A139. The laboratory analytical results of the samples previously collected indicate that this material does not contain asbestos.

3.1.6 Plaster

Wall plaster (Grey) on diamond mesh lath was observed in Room B215N. The laboratory analytical results of samples previously collected indicate that this material contains **1% Tremolite asbestos**. This material is considered friable and was observed to be in fair condition. MPL identified visually similar ceiling plaster on diamond mesh lath in Rooms C100D and A142 and noted to be in poor condition.

Wall and column plaster was previously sampled from Room A139. The laboratory analytical results of the samples collected indicate that this material does not contain asbestos.

Ceiling plaster (Gray) was observed on a concrete ceiling deck and previously sampled from Room D108. The laboratory analytical results of the samples collected indicate that this material does not contain asbestos.

3.1.7 Drywall Joint Compound

Drywall joint compound was observed throughout the subject building and previously sampled from the following locations: A136, A139A, C115, B215, C200, E146, E053 and E038. The laboratory analytical results of drywall joint compound samples previously collected from these locations indicate that this material does not contain asbestos.

3.1.8 Ceiling Tiles

Ceiling tiles were observed in various locations throughout the subject building.

- Suspended ceiling tiles (2'x4'-Pinhole with Large Fissures) were observed in Room A106. The laboratory analytical results of the samples previously collected indicate that this material does not contain asbestos.
- Suspended ceiling tiles (2'x4'-Fissures) were observed in Room A036. The laboratory analytical results of the samples previously collected indicate that this material does not contain asbestos.
- Glued on Acoustic Ceiling Tile (12"x12"-with Uniform Holes) was observed in the Men's Change Room in D108. The laboratory analytical results of the samples previously collected indicate that this material and its associated mastic (Brown) do not contain asbestos.

3.1.9 Vinyl Floor Tiles

Several different types of vinyl floor tiles were observed and previously sampled within the building as follows:

- Vinyl floor tiles (12"x12"-White w/ Beige Spots) was previously identified to **contain 6.5% Chrysotile asbestos** was observed in Room C144 and C110. This material is considered non-friable and was observed to be in poor condition.
- Vinyl floor tiles (12"x12" – Red with flakes) were previously observed in Room A106C. The laboratory analytical results of the vinyl floor tile samples collected indicate that this material and its associated mastic (black) does not contain asbestos.
- Vinyl floor tiles (2'x2' – Offwhite) were previously observed in Room B215E. The laboratory analytical results of the vinyl floor tile samples collected indicate that this material does not contain asbestos.
- Vinyl floor tiles (12"x12" – Offwhite with grey and black flakes) were previously observed in Room C209. The laboratory analytical results of the vinyl floor tile samples collected indicate that this material and its associated mastic (black) does not contain asbestos.

- Vinyl floor tiles (12"x12" – Beige with Multicolour flakes) were observed in Room C209. The laboratory analytical results of the vinyl floor tile samples previously collected indicate that this material and its associated mastic (black) does not contain asbestos.
- Vinyl floor tiles (12"x12" – Offwhite with grey flakes) were observed in the C200 Hallway. The laboratory analytical results of the vinyl floor tile samples collected indicate that this material and its associated mastic (black) does not contain asbestos.
- Vinyl floor tiles (12"x12" – Pink with dots) were observed in Room C115. The laboratory analytical results of the vinyl floor tile samples previously collected indicate that this material and its associated mastic (black) does not contain asbestos.
- Vinyl floor tiles (12"x12" – Off-white with dots) were observed in Room C115. The laboratory analytical results of the vinyl floor tile samples previously collected indicate that this material and its associated mastic (black) does not contain asbestos.
- Vinyl floor tiles (12"x12" – Offwhite with blue streaks) were observed in Room E041. The laboratory analytical results of the vinyl floor tile samples previously collected indicate that this material and its associated mastic (yellow) does not contain asbestos.
- Vinyl floor tiles (12"x12" – Grey with white and light grey streaks) were observed in Room E053. The laboratory analytical results of the vinyl floor tile samples previously collected indicate that this material and its associated mastic (yellow) does not contain asbestos.
- Vinyl floor tiles (12"x12" – Offwhite with grey streaks) were observed in Room E224. The laboratory analytical results of the vinyl floor tile samples previously collected indicate that this material and its associated mastic (black) does not contain asbestos.

3.1.10 Levelling Compound

Floor levelling compound was previously sampled from Room A140. The laboratory analytical results indicate that this material does not contain asbestos.

Floor levelling compound was previously sampled from Room A122. The laboratory analytical results indicate that this material does not contain asbestos.

3.1.11 Concrete Block Mortar

Concrete block mortar was previously sampled from the interior of the building in Room A142. The laboratory analytical results indicate that this material does not contain asbestos.

3.1.12 Ceramic Wall / Floor Tile Grout

Ceramic wall tile (Grey) grout was previously sampled from the A106C. The laboratory analytical results indicate that this material does not contain asbestos.

3.1.13 Transite (Asbestos Cement)

Transite materials was observed as segments of conduit pipe in Room A138C. To avoid possible damage, no bulk samples of the transite piping were collected. However, this material is **known to contain asbestos**. This material is considered to be non-friable and was observed in good condition.

3.1.14 Caulking

Interior window caulking (Black) was previously sampled from Room A139. The laboratory analytical results indicate that this material **contains 2% Chrysotile asbestos**. This material is considered non-friable and was observed to be in good condition.

3.1.15 Cementitious Coating

Cementitious floor levelling compound was observed in Room A140. The laboratory analytical results of cementitious coating samples collected indicate that this material does not contain asbestos.

High traffic floor coating was observed in Room A144. The laboratory analytical results of cementitious coating samples previously collected indicate that this material does not contain asbestos.

3.1.16 Mastic

Carpet mastic (Brown) was previously sampled from Room B202B. The laboratory analytical results indicate that this material does not contain asbestos.

3.1.17 Tar

Previously identified roofing tar (Black) was previously sampled from the roof level of the subject building. The laboratory analytical results for the samples collected indicate that the material does not contain asbestos.

3.1.18 Fire Door

Fire doors were observed at various locations throughout the subject building. To avoid possible damage, no bulk samples of the internal door insulation materials were collected. Prior to removal and/or replacement, fire doors should be examined and tested for asbestos content. Fire doors should be considered to contain asbestos until bulk samples and analysis proves otherwise. All fire doors were observed to be in good condition.

3.1.19 Roofing Material

To avoid damage and compromising the integrity of roofing material, no bulk samples of the roofing materials were collected. Prior to removal and/or replacement, roofing materials should be examined and tested for asbestos content. Roofing materials should be considered to contain asbestos until bulk samples and analysis proves otherwise.

Recommendations

- Asbestos-containing materials identified to be in poor condition must be repaired/removed immediately, following Type 1/2/3 asbestos abatement work procedures as detailed in O. Reg. 278/05 and disposed of as asbestos waste under O. Reg. 347;
- Asbestos-containing materials that have been identified to be in fair condition should be either repaired (where possible) and/or closely monitored for signs of further deterioration. Depending on type of material and location, these materials should be scheduled for removal if there is potential risk of exposure to the worker and/or occupants;
- Materials identified to contain asbestos that are in good condition and do not pose a risk to workers or occupants can be managed in place. Prior to renovation/demolition activities that may disturb the ACMs, these materials must be removed following appropriate Type 1/2/3 asbestos abatement work procedures as detailed in O. Reg. 278/05 and disposed of as asbestos waste under O. Reg. 347;
- Please refer to Appendix E – Asbestos-Containing Materials Checklist for material conditions, quantities (where applicable) and recommended actions.
- Prior to renovation/demolition of materials which are assumed to be asbestos-containing (suspect materials which were not sampled, i.e., roofing materials, flexible duct connectors, fire doors and suspect transite), these materials must either be tested for asbestos content or removed following appropriate asbestos abatement work procedures (Type 1/2/3) as detailed in O. Reg. 278/05 and disposed of as asbestos waste under O. Reg. 347;
- All repairs or removal of asbestos-containing materials must be conducted according to Ontario Regulation 278/05, Regulation respecting Asbestos on Construction Projects and in Buildings and Repair Operations - made under the Occupational Health and Safety Act. Asbestos containing waste must also be handled and disposed of according to Ontario Regulation 347/90 as amended – made under the Environmental Protection Act. Any suspect building materials encountered that were not assessed as part of this survey, should be assumed to contain asbestos until proven otherwise by analytical testing;
- Sub-trades working with or in close proximity to asbestos-containing material should be informed of its presence; and
- Given that asbestos containing materials (ACMs) have been identified and will likely remain in place, an Asbestos Management Plan (AMP) is therefore required and an inventory of ACMs must be kept on site. All ACMs must be routinely inspected to ensure no damage has occurred, and the inventory must be updated once in each 12-month period and as may be required based on expected changing site conditions, abatement and/or renovation activities

3.2 Lead

Findings

3.2.1 Paint Finishes

A total of eight (8) paint samples from the subject building were previously collected and analyzed for lead content. Results of bulk sampling testing are summarized in Table 2 and the laboratory certificate of analysis can be found in Appendix C.

Table 2:
Lead Sampling Locations and Laboratory Results

| Sample I.D. | Location | Material | Colour | Lead Concentration Weight by Conc. (%) |
|--|------------------------------|-------------------|-----------|---|
| Pb-01 | A140 – Above door vent | Paint | Beige | 0.0753 |
| Pb-02 | A140 – Door | Paint | Blue | 0.0008 |
| Pb-03 | A144 – Floor | Paint | Beige | 0.0173 |
| Pb-04 | D109 – Wall | Paint | Maroon | <0.0019 |
| Pb-05 | A122 – Wall | Paint | Black | 0.0579 |
| Pb-06 | D201 – Ducts | Paint | White | 0.167 |
| Pb-07 | B208B Wall | Paint | Green | 0.0006 |
| Pb-08 | E254 – Wall | Paint | Off white | 0.0020 |
| Previously Sampled Lead Paint Finishes | | | | |
| Sample I.D. | Location | Material | Colour | Lead Concentration Weight by Conc. (%) |
| 060-D-2-LBP- 013107-05 | D201 | Air Handling Unit | White | 0.19 |
| 060-B-1-LBP- 013107-09 | B157 | Columns | White | 0.08 |
| 060-B-1-LBP- 013107-13 | B-Stairwell | Doors | Red | 0.06 |
| 060-E-B -LBP - 013107-15 | E010 | Walls | White | 0.06 |
| 060-E-1-LBP- 013107-19 | Hallway E100 | Doors and Frames | Blue | 0.11 |
| 060-E-2-LBP- 013107-22 | E218 | Doors and Frames | Brown | 1.00 |

| Sample I.D. | Location | Material | Colour | Lead Concentration Weight by Conc. (%) |
|-----------------------|-----------------|-------------------|--------|---|
| 060-A-1-LBP-013107-23 | A139 | Walls | White | 0.09 |
| 060-A-1-LBP-013107-28 | A131 | Doors and Lockers | Blue | 1.90 |
| 060-A-1-LBP-013107-29 | Hallway at A130 | Lockers | Yellow | 2.90 |

The paint finishes highlighted in blue in the above table were determined to contain low concentrations of lead which are less than 0.1%. These paint finishes were observed to be in good to poor condition.

The paint finishes highlighted in pink in the above table are considered lead-containing paints or surface coatings with concentrations which are greater than 0.1%. These paint finishes were observed to be in good to poor condition.

All remaining paints tested were below the laboratory limit of detection for lead. The laboratory certificate of analysis for the paint sample is also included in Appendix C.

However, all other paints throughout the subject building that are not mentioned in this report must be considered to be lead-containing unless sampling and analysis proves otherwise.

3.2.2 Battery Packs

MPL identified lead-containing acid battery packs throughout the subject building. These battery packs were observed on walls and above exits throughout the surveyed building.

Lead may also be present in the following materials in the building:

- Solder used on copper domestic water lines;
- Solder used in bell fittings for cast iron pipes;
- Solder used in electrical equipment;
- Ceramic tile glaze; and
- Concrete and mortar products, etc.

3.2.3 Lead Shielding

MPL observed diagnostic equipment suspected to contain radioactive materials within Room E029. Lead shielding material is suspected to be present within the walls of E029.

Recommendations

Paints identified to contain lead that are in poor condition must be immediately repaired and/or stabilized following a minimum Type 1/2 lead abatement procedures as per the OMOL Guideline "Lead on Construction Project" dated April 2011.

Paints identified to contain lead that are in fair condition should be either repaired (where possible) and/or closely monitored for signs of further deterioration.

Paints identified to contain lead that are in good condition and do not pose a risk to workers or occupants can be managed in place.

Detailed worker protection protocols are outlined in the OMOL Guideline “Lead on Construction Projects” dated April 2011. Generally, the removal of the lead-based paint with the use of a chemical gel or paste, or a power tool equipped with a HEPA filter is considered a Type 1 operation. The removal of lead-based paint by scraping or sanding using non-powered hand tools is considered a Type 2 operation. The removal of lead-based paint using abrasive blasting, or power tools without a HEPA filter, is considered a Type 3 operation, and requires the most stringent worker protection protocols (similar to asbestos); Furthermore, high temperature cutting or welding would also require Type 3 Operations under the Guideline for Lead on Construction Projects. If this type of work is required, it may be prudent to chemically remove the lead paint in selected locations prior to performing any high temperature cutting or welding.

All lead materials that are removed must follow the Ministry of Labour and Environmental Abatement Council of Ontario Lead Guidelines.

Please refer to Appendix F – Hazardous Materials Checklist for material conditions, quantities (where applicable) and recommended actions.

Precautions should be taken as required during major renovations and demolition projects to ensure that workers’ exposure levels to airborne lead does not exceed 0.05 mg/m³.

This can be achieved by:

- Provide workers with proper training;
- Providing the workers with respiratory protection;
- Wetting the surface of the materials to prevent dust emissions; and,
- Providing workers with hygiene facilities to properly wash prior to exiting the work area.

Sub-trades working with or in close proximity to lead based paint should be informed of its presence.

All waste material must be handled and disposed of according to the Revised Regulation of Ontario 347/90 as amended – made under the Environmental Protection Act. Lead waste generated may also be subject to Leachate Criteria (Schedule 4) of this regulation.

3.3 Mercury

Findings

3.3.1 Thermostat Switches

MPL did not observe thermostats containing liquid mercury within the subject building.

3.3.2 Fluorescent Light Tubes

MPL identified fluorescent light fixtures throughout the surveyed area containing 2 to 4 fluorescent light tubes per fixture. Mercury is likely to be present in vapor form in the fluorescent light tubes.

3.3.3 Pressure Gauges and Float Switches

MPL identified pressure gauges containing liquid mercury in mechanical rooms throughout the subject building. MPL also identified suspected float switches that may contain liquid mercury within Room A02 and C02. They were observed in good condition.

Recommendations

Please refer to Appendix F – Hazardous Materials Checklist for material conditions, quantities (where applicable) and recommended actions.

Precautions must be taken to prevent mercury liquid/vapours from becoming airborne during building demolition. Exposure to mercury is regulated under Ontario Regulation 490/09, Designated Substances - made under the Occupational Health and Safety Act.” Prior to renovations to the building, all mercury containing fluorescent light tubes, thermostats, and equipment must be removed and stored in a safe, secure location and/or properly disposed of in accordance with R.R.O. 1990, Regulation 347 General – Waste Management, made under the Environmental Protection Act.

3.4 Silica

Findings

Silica is expected to be present in building materials such as concrete, brick, mortar and ceramic tiles located throughout the structures. Free crystalline silica (α -Quartz) may be a component in ceiling tiles and gypsum board. Silica (including free crystalline silica) may also be a component of concrete and brick surfaces noted in the building.

Recommendations

Precautions should be taken as required during major renovations and demolition projects on concrete (i.e. coring through concrete slabs, demolition of masonry, etc.) to ensure that workers’ exposure levels to airborne silica does not exceed 0.05 mg/m³.

This can be achieved by:

- Provide workers with proper training;
- Providing the workers with respiratory protection;
- Wetting the surface of the materials to prevent dust emissions; and,
- Providing workers with facilities to properly wash prior to exiting the work area.

Demolition work that is likely to impact silica-containing materials should be carried out in accordance with the requirement detailed in the Ontario Ministry of Labour document entitled “Guideline: Silica on Construction Projects”, dated April 2011.

Other Hazardous Materials

3.5 Polychlorinated Biphenyls (PCBs)

Findings

3.5.1 Light Ballasts

The subject building is illuminated by LED and fluorescent lights. MPL assessed representative ballasts in the building, and these ballasts were identified as non-PCBs content. These light ballasts were observed to be manufactured by Sylvannia.

3.5.2 Transformers

MPL did not observe any PCBs containing electrical transformers within the subject building.

Recommendations

Please refer to Appendix F – Hazardous Materials Checklist for material conditions, quantities (where applicable) and recommended actions.

Prior to any renovations, all light ballasts and HID lamps containing or suspected of containing PCBs that will be affected by the work, must be decommissioned by a licensed contractor such that PCBs are contained and not released to the environment during decommissioning and properly disposed of in accordance with R.R.O. 1990, Regulation 347 General – Waste Management, made under the Environmental Protection Act.

3.6 Ozone Depleting Substances (ODSs) and Other Halocarbon

Findings

A visual assessment was conducted to identify equipment potentially containing ODSs and other halocarbons. MPL observed standard refrigeration units within office spaces within the subject building. In addition to standard refrigeration units, MPL also observed various equipment containing ODSs within laboratories and mechanical rooms within the surveyed building.

Recommendations

Please refer to Appendix F – Hazardous Materials Checklist for material conditions, quantities (where applicable) and recommended actions.

Under the management of a licensed contractor, equipment containing R4100A, R407, R404 and R134A do not represent a significant threat to human health or the environment however, a licensed contractor must

decommission equipment such that CFCs are contained and not released to the environment during servicing or operation.

3.7 Radioactive Materials

Findings

A visual assessment of the subject building was conducted to determine if any electrical components containing radioactive materials were present. MPL did not observe any electrical components containing radioactive materials.

MPL observed GE-brand Medical Systems diagnostic equipment containing suspected radioactive materials within Room E029. This equipment was observed to be in good condition.

Recommendations

Please refer to Appendix F – Hazardous Materials Checklist for material conditions, quantities (where applicable) and recommended actions.

Under the management of licensed contractor, equipment containing radioactive materials must be decommissioned such that radioactive materials are contained and not released to the environment during decommissioning as per O.Reg. 347/09.

3.8 Underground and Above Ground Storage Tanks (USTs and ASTs)

Findings

A visual survey of the subject building was conducted to determine if any USTs and ASTs were present. No USTs and ASTs were observed within the surveyed area.

Recommendations

Since no underground and/or above ground storage tanks (USTs and ASTs) were observed or suspected to be present during the site survey, no further action is required.

3.9 Mould

Findings

3.9.1 Mould

A visual survey of the subject building was conducted to determine if any mould was present. MPL did not observe any obvious signs of visible mould within the subject building.

3.9.2 Water Damage

A visual survey of the subject building was conducted to determine if any water damaged was present. MPL did not identified any areas throughout the subject building, where materials were affected by water damage.

Recommendations

- Please refer to Appendix F – Hazardous Materials Checklist for material conditions, quantities (where applicable) and recommended actions.
- Water stained/damaged ceiling tiles, floor tiles and drywall were observed throughout the subject building should be replaced as part of regular maintenance and the underlying cause of the water leakage should be identified and repaired.

This report should be made available to contractors tendering on any renovation or demolition work. In turn, all contractors requesting tenders from subcontractors shall furnish this report to subcontractors.

4.0 GENERAL CONSIDERATIONS AND LIMITATIONS

The information presented in this report is based on information provided by others, direct visual observation made by personnel with **McIntosh Perry Limited (MPL)**, and the results of laboratory testing as identified herein.

It should be noted that there might be hazardous materials in locations not visible during our investigation. In the event such material is encountered during demolition operations in the building, this material should be tested and dealt with accordingly.

The findings detailed in this report are based upon the information available at the time of preparation of the report. No investigative method eliminates the possibility of obtaining imprecise or incomplete information. Professional judgement was exercised in gathering and analyzing the information obtained and in the formulation of our conclusions and recommendations.

MPL does not certify or warrant the environmental status of the property nor the building on the property.

Please note that the passage of time affects the information provided in the report. Environmental conditions of a site can change. Opinions relating to the site conditions are based upon information that existed at the time that the conclusions were formulated.

The client expressly agrees that it has entered into this agreement with MPL, both on its own behalf and as agent on behalf of its employees and principals.

The client expressly agrees that MPL's employees and principals shall have no personal liability to the client in respect of a claim, whether in contract, tort and/or any other cause of action in law. Accordingly, the client expressly agrees that it will bring no proceedings and take no action in any court of law against any of MPL's employees or principals in their personal capacity.

We trust that we have detailed our findings clearly and that we have satisfactorily addressed the scope of work you require at this time. In the event you wish us to review our findings with you, or require our services further in this regard, please do not hesitate to contact our office.

Yours truly,

MCINTOSH PERRY LIMITED



Pegah Parichehreh, M.Sc.
Project Technician
Hazardous Materials/ Environmental Health & Safety



John Tufts, B.Sc.
Project Manager
Hazardous Materials/ Environmental Health & Safety

APPENDIX A

Regulatory Requirements

REGULATORY REQUIREMENTS

In Ontario, there is a total of eleven Designated Substances. These substances have been regulated under Ontario Regulation 490/09 — *Designated Substances*, made under the Ontario Health and Safety Act, which applies to controlling designated substances in the workplace.

In addition to the Ontario Regulation 490/09 noted above, the following were observed for this survey:

Guideline: Lead on Construction Projects, issued April 2011 by the Occupational Health and Safety branch of the Ministry of Labour

Guideline: Silica on Construction Projects issued April 2011 by the Occupational Health and Safety branch of the Ministry of Labour.

The Occupational Health and Safety Act (OHSA), R.S.O. 1990, c.0.1, s.30 (1) specifies that: “Before beginning a project, the owner shall determine whether any Designated Substances are present at the project site and shall prepare a list of all Designated Substances that are present at the site.

Section 30 of The Act requires that the list of Designated Substances be provided to prospective contractors and subcontractors who may do work on a site and come into contact at the site with Designated Substances.

The Ministry of Labour has designated the following substances:

- Acrylonitrile
- Arsenic
- Asbestos
- Benzene
- Coke Oven Emissions
- Ethylene Oxide
- Isocyanates
- Lead
- Mercury
- Silica
- Vinyl Chloride

Ontario Regulation 278/05 (O. Reg. 278/05), the Regulation respecting Asbestos on Construction Projects and in Buildings and Repair Operations, made under the Occupational Health and Safety Act (OHSA), requires owners of a building to identify Asbestos-containing Materials (ACMs) prior to potential disturbance of the materials.

In addition, an owner of a building is required to have an Asbestos Management Plan (AMP) if ACMs (friable or non-friable) are present in the building and are to remain in place. An inventory of ACMs must be kept on site. All ACMs must be routinely inspected to ensure no damage has occurred, and the inventory must be updated once in each 12-month period and as may be required based on expected changing site conditions, abatement and/or renovation activities. Removal of all asbestos containing materials is required prior to building demolition.

In addition to the Designated Substances, the building was also surveyed for the presence of other hazardous materials such as polychlorinated biphenyls (PCBs), radioactive materials, ozone depleting substances (ODSs), other halocarbons, and mould.

We understand that this survey has been conducted to comply with the regulatory requirements of Ontario Regulation 278/05.

APPENDIX B

Survey Methodology & Background Information

SURVEY METHODOLOGY

For the purpose of this survey, not all Designated Substances or suspect hazardous material were sampled. Selective sampling was carried out only for substances that were suspected to be present or those deemed to have a likely source of origin in the survey areas.

Materials that were homogeneous in nature and/or similar in appearance to other materials tested were considered to be of similar composition. The likelihood of ACMs being present in inaccessible areas such as above gypsum board ceilings or behind gypsum wallboards was determined by assessing the presence of asbestos-containing systems in adjacent areas. Equipment such as boilers, motors, blowers, electrical panels, fire doors etc., were not de-energized or disassembled to examine internal components or materials. These items should be considered to contain hazardous materials until proven otherwise.

During the survey, representative samples of suspect building materials were collected and sent to AIHA accredited independent laboratory for analysis. Laboratory Certificate of Analysis are attached in Appendix A.

Other potential hazardous materials were identified by visual observation and/or by reviewing Material Safety Data Sheets (MSDS) and/or safety labels where available.

Investigated Areas

The survey included all accessible areas and ceiling space within subject building as required under our scope of work. No destructive investigations were performed as part of this survey. Photographs of the areas investigated can be found in Appendix D.

The assessment was directed on the interior structure and finishes of the building. It did not consider current or past owner or occupant articles within the building (i.e. contents, furniture, etc.) and does not report on possible contaminants in the soil under and surrounding the building, or contents of vessels, drums, etc. that may be concealed.

Sampling and Assessment Methodologies

Sampling was conducted as part of this assessment. Results for asbestos and lead samples can be found in the Findings & Recommendation Section 3.0.

A historical review of previous designated substance survey reports and abatement reports was examined as part of this survey. Due to concerns regarding certain historical analytical results, mainly in 2008 and prior years, confirmatory re-sampling was conducted for selected materials previously identified not to contain asbestos. However, building materials previously identified to be asbestos-containing were not re-sampled. The reports are listed as follows:

- Designated Substance Survey by Conestoga-Rovers & Associates (dated April 2007, reference # 45870(18));
- Asbestos Abatement Letter by Conestoga-Rovers & Associates (dated August 24, 2007, reference#49318);
- Asbestos Sampling – 200 Lees Avenue, E-Block Penthouse by Conestoga-Rovers (dated April 8, 2009, reference # 05659Memo-1);

- Project Specific Asbestos Sampling Report-200 Lees Avenue, Room A122 by EHS Partnerships (dated August 9, 2011, reference#04-0033-11-018);
- Project Specific Lead Testing Report, Room A139 by EHS Partnerships LTD (dated August 16, 2011, reference # 04-0033-11-020);
- Asbestos Abatement & Laboratory Decommissioning, A-Block by EHS Partnerships LTD (dated March 16, 2012, reference # 04-033-11-025);
- Asbestos Sampling Report – Soil, C-Block Crawlspace, 200 Lees Avenue, University of Ottawa by EHS Partnerships LTD (dated May 14, 2012, reference#04-0033-12-012);
- Post Remedial Asbestos Investigation and Sampling Report-Soil Southeast Quadrant of A-Block Crawlspace, 200 Lees Avenue by EHS Partnerships (dated May 28, 2012, reference# 04-0033-12-025);
- Post Remedial Asbestos Investigation and Sampling Report-Soil Northwest Quadrant of A-Block Crawlspace, 200 Lees Avenue by EHS Partnerships (dated June 7, 2012, reference# 04-0033-12-015);
- Asbestos Sampling Report – Soil, B-Block Crawlspace, 200 Lees Avenue, University of Ottawa by EHS Partnerships LTD (dated July 30, 2012, reference#04-0033-12-012);
- Asbestos Abatement – Type 2 Glovebag Operations, 200 Lees Avenue – B Block Crawlspace by EHS Partnerships LTD (dated January 11, 2013, reference #04-0033-12-047);
- Asbestos Sampling Report – Soil, D-Block Crawlspace, 200 Lees Avenue, University of Ottawa by EHS Partnerships LTD (dated March 6, 2013, reference#04-0033-13-011);
- Asbestos Sampling Report – Soil, D-Block Crawlspace, 200 Lees Avenue, University of Ottawa by EHS Partnerships LTD (dated April 23, 2013, reference#04-0033-018);
- Pre-Construction Asbestos Containing Material Assessment, 200 Lees Avenue-Room A142 by EHS Partnerships LTD (dated May 22, 2013, reference #04-0033-13-017);
- Asbestos containing Materials Abatement - 200 Lees Avenue, Ottawa Ontario by EHS Partnerships LTD (dated July 23, 2013, reference # 04-0033-017);
- Project Specific Asbestos Sampling Report – 200 Lees Avenue-Block D Ceiling Tiles by EHS Partnerships LTD (dated February 3, 2014, reference # 04-0033-14-006);
- Project Specific Designated Substance Survey, 200 Lees-Roof Access Project by CM3 Environmental (dated July 7, 2017, reference#TLW-1443);
- As Built Specification-Bicycle COOP(Rental) by University of Ottawa (drawings dated January 5, 2011, Project Reference#089-008-060);
- As Built Specifications-200 Lees Campus-Lecture Rooms A130&A131 Cooling and Ventilation Upgrade by Goodkey Weedmark Consulting Engineers (drawings dated October 2011, Project Reference #112-001-060);
- As Built Specification-Installation of Automatic Door Opener by University of Ottawa (drawings dated January 26, 2012, Project Reference#101-002-060);
- As Built Specification-Retrofit 060-E155D for Linda McLean Research Clinic by University of Ottawa (drawings dated December 8, 2014, Project #145-001-060); and

- As Built Specification- Visual Arts Miscellaneous Renovations in Rooms E020, E050, E244 by University of Ottawa (drawings dated May 2017, Project No. BT15-86206).

Asbestos

Background Information on Asbestos

Asbestos is a generic name that has been given to a group of naturally occurring fibrous minerals. In the past, asbestos was commonly used as a component in building materials such as insulation, fireproofing and acoustic or decorative panels. Although there are many types of asbestos, the three main forms of commercial importance in Ontario are chrysotile, amosite and crocidolite.

An Asbestos-Containing Material (ACM) is defined by O. Reg. 278/05 as a material that contains 0.5% or more asbestos by dry weight. ACMs are placed into two general classes, “friable” and “non-friable” ACMs. Friable ACMs are those materials that when dry can be crumbled, pulverized and reduced to powder by hand pressure. Typical friable ACMs include acoustical or decorative texture coats, fireproofing and thermal insulation. Non-friable ACMs are much more durable as they are held together by a binder such as cement, vinyl or asphalt. Typical non-friable ACMs include floor tiles, fire blankets, roofing materials and cementitious products such as wallboards, pipes or siding.

It has been recognized that hazardous situations may exist in buildings where asbestos-containing materials are found. This is especially true where asbestos fibres may become airborne as a result of material ageing, physical damage, and water damage or air movement.

In contrast, there is little reason for concern if the asbestos is in good condition, has not been damaged and is not in a location where it is likely to be disturbed.

Asbestos Survey Methodology

The asbestos survey included the identification of potential friable and non-friable asbestos-containing materials within the surveyed areas of the subject building.

The likelihood of ACMs being present in inaccessible areas such as above gypsum wallboard ceilings and walls was determined by assessing the presence of asbestos-containing materials in adjacent areas.

Fiberglass insulation was not submitted for analysis as it can be identified visually as non-asbestos material.

Building materials suspected of containing asbestos were identified and representative sampling and laboratory testing of these materials was conducted. The number of bulk material samples collected from a homogeneous area was in accordance with Table 1. O. Reg. 278/05 s. 3 (3) below. Building materials suspected of containing asbestos were collected using wetting techniques and hand sampling tools.

Table 1 - O. Reg. 278/05 s. 3(3): Minimum Asbestos Bulk Material Sample Requirements

| Item | Type of material | Size of area of homogeneous material | Minimum number of bulk material samples to be collected |
|------|------------------|--------------------------------------|---|
| 1. | | Less than 90 square metres | 3 |

| | | | |
|----|--|---|---|
| | Surfacing material, including without limitation, material that is applied to surfaces by spraying, by troweling or otherwise, such as acoustical plaster on ceilings and fireproofing materials on structural members | 90 or more square metres, but less than 450 square metres | 5 |
| | | 450 or more square metres | 7 |
| 2. | Thermal insulation, except as described in item 3 | any size | 3 |
| 3. | Thermal insulation patch | Less than 2 linear metres or 0.5 square metres | 1 |
| 4. | Other material | Any size | 3 |

Preliminary identification of the samples was made using polarized light microscopy (PLM), with confirmation of presence and type of asbestos made by dispersion staining optical microscopy. This analytical procedure follows the U.S. Environmental Protection Agency Test Method EPA/600/R-93/116 Method for the Determination of Asbestos in Bulk Building Materials, June 1993.

All bulk samples were analysed for asbestos content by Paracel Laboratories Ltd., an independent laboratory. Paracel is a fully accredited facility for asbestos analysis and is accredited under National Voluntary Laboratory Accreditation (NVLAP Lab Codes 200812-0 and 200863-0). Paracel is accredited for asbestos bulk analysis in PLM in Ottawa and Mississauga, respectively. For the Scope of Accreditation under the (CALA) Membership Number 1262, Paracel is accredited for asbestos in air samples by PCM.

Vinyl floors tiles were analyzed using the phase light microscopy (PLM) method of analysis. However, given the composition of vinyl floor products, the PLM analysis method may be prone to yielding false negative analytical results. Therefore, prior to removal or replacement, vinyl floor products previously identified to be negative, should undergo additional analysis by Transmission Electron Microscopy (TEM) to confirm asbestos content, if any.

Materials identified to contain asbestos were assessed on the relative possibility of fibre release into the air due to a combination of their condition and accessibility. *Evaluation of ACMs Based on Condition*

In evaluating an ACM's condition, the following criteria was applied:

- **Good** – Material shows no signs of damage and/or is encapsulated. Asbestos-containing material could remain in place until eventual building demolition or major renovation.
- **Fair** – Material shows signs of minor damage (<5% damage) or otherwise near the end of useful life. This includes minor shrinking, cracking, delamination and/ or other damage. Material should be monitored closely and scheduled to be repaired, encapsulated or removed.
- **Poor** – Damage is greater than 5% to any ACM material and is highly recommended to be removed, repaired or encapsulated.

Note: The above evaluation criteria was also applied to other hazardous materials where applicable. Please refer to the Asbestos and Hazardous Materials Checklist in Appendix E & F for further details.

Lead

Background Information on Lead

Lead was a common additive in exterior and hard-wearing paint applications. Lead was used to prolong shelf life of paint and to increase its flexibility and durability to wear and weather. Acute exposure to lead by inhalation or ingestion may cause headaches, fatigue, nausea, abdominal cramps and joint pain. Chronic exposures can cause reduced haemoglobin production and reduced lifespan. It has also been known to impact the body's central and peripheral nervous systems and brain function and has been linked to learning disabilities in children.

Currently in Ontario, there is no regulatory limit that determines what concentration of lead constitutes a "lead containing material". On October 21, 2010, Health Canada, under the *Hazardous Products Act*, stated that the lead content in surface-coating materials, furniture, toys and other articles for children, should not exceed 90 mg/kg (0.009%, 90 ppm). However, this is intended for the importation or sale of products within Canada. Therefore, this is not to be misconstrued as a limit established to define a lead-containing material or a limit with respect to lead on construction projects.

The Environmental Abatement Council of Canada (EACC) has also developed the "*Lead Guideline for Construction, Renovation, Maintenance or Repair*" dated October 2014, which discusses the classification, handling, disturbance and removal of lead-containing materials. For the purpose of this guideline, paints or surface coatings containing less than or equal to 0.1% lead by weight (1000 mg/kg or 1000 ppm) are considered low-level lead paints or surface coatings. If these materials (and their respective surfaces) are disturbed in a non-aggressive manner and performed using adequate dust control procedures, then worker protection from the inhalation of lead is not required.

Furthermore, paints or surface coatings containing greater than 0.1% lead by weight are considered lead-containing paints or surface coatings. If these materials (and their respective surfaces) are disturbed, appropriate lead abatement procedures must always be followed.

Exposure to lead-containing materials is regulated under Ontario Regulation 490/09, *Designated Substances* - made under the Occupational Health and Safety Act. Care must be taken to prevent lead-containing particles from becoming airborne during the disturbance of lead-containing surfaces (i.e., during renovation or demolition projects). All lead abatement work must follow procedures outlined in the Guideline Lead on Construction Projects, issued in September 2004 (amended in April 2011) by the Occupational Health and Safety branch of the Ministry of Labour (Type 1-3). Similarly, the lead abatement work procedures outlined in the EACC Lead Guideline for Construction, Renovation, Maintenance or Repair (October 2014) may also be implemented (Class 1-3).

Lead is known to have been used in solder on copper plumbing fixtures, in lead conduit pipes, in lead-calcium battery plates, ammunition, and in nuclear and X-ray shielding devices. However, these materials were not sampled during this investigation, but were noted where applicable.

To verify lead content in paints, representative bulk samples of paint and finishes suspected of containing lead were collected. Bulk samples were scraped down to the building base structure, with all possible layer's present, placed in sealed plastic bags and labeled; and then submitted to an independent laboratory for analysis. Samples were treated with a dilute nitric acid sample digestion prior to filtration. Analysis utilized for lead detection in filtered samples was inductively coupled plasma optical emission spectrometry (ICP-OES).

Mercury

Background Information on Mercury

Mercury is known to cause poisoning in humans through the inhalation of vapours, ingestion of contaminated materials or skin absorption through direct contact with the liquid.

Precautions must be taken to prevent mercury vapours from becoming airborne during renovations or demolition of the building. Exposure to airborne mercury is regulated under the Revised O. Reg. 490/09 as amended – Regulation respecting Mercury – made under the Occupational Health and Safety Act; and under O. Reg. 558, which amended O. Reg. 347/90 (General - Waste Management), mercury is classified as a Schedule 2(b) Hazardous Waste Chemical. Its hazardous waste number is U151.

Mercury is found in products such as thermostats, temperature and pressure gauges, fluorescent lamps and batteries. Mercury in products can be released to the environment through breakage, or disposal at the end of a product's useful life. Improper disposal of these mercury products poses a health and environmental risk to everyone. In addition, the disposal of mercury-containing products can create wastes that are often classified as hazardous. Wastes that leach mercury in concentrations exceeding Ontario Regulation 347/90 (General - Waste Management) limits are also considered hazardous.

The mercury in thermostat switch contains approximately 3-4 grams of mercury in a glass ampoule, typically attached to a metal coil. Mercury-containing switches have been used in thermostats for over 40 years.

Mercury is an essential component in fluorescent lamps and HID lamps. The mercury is in a vapour form and in the phosphor coating on the lamp tube. Estimates of the mercury content contained in compact, 4 foot, and 8-foot lamps are 10 mg, 23 mg, and 46 mg respectively.

Most fluorescent lamps qualify as hazardous waste when removed from service and are therefore prohibited from disposal in the solid waste stream. Fluorescent lamps would be classified as 146T on your facility Generator Registration Report under O. Reg. 347/90 - General Waste Management, as amended by O. Reg. 558/00. Under this regulation, if the leachate results exceed 0.1 milligrams of mercury per litre for a given waste, then the facility must treat the waste as hazardous waste. Most fluorescent and HID lamps will exceed the leachate toxicity limit; therefore, these wastes must be registered and treated as hazardous waste or sent for recycling.

Silica

Background Information on Silica

Silica is expected to be present in building materials such as concrete, brick, mortar and ceramic tiles located throughout the structures. Free crystalline silica (α-Quartz) may be a component in ceiling tiles and gypsum board. Silica (including free crystalline silica) may also be a component of concrete and brick surfaces noted in the building.

Exposure to airborne silica is regulated under Ontario Regulation 490/09, *Designated Substances* - made under the Occupational Health and Safety Act.

Polychlorinated Biphenyls (PCBs)

Background Information on PCBs

Polychlorinated Biphenyls (PCBs) were commonly used as dielectric insulating fluid in electrical equipment such as transformers and capacitors, and in the fluorescent and HID lamp ballasts. The production of PCBs in the North America started in 1929 and was banned at the beginning of 1979. After 1981, no manufacturers produced fluorescent and HID lamps with PCB-containing ballasts. PCBs are not a designated substance under the Occupational Health and Safety Act.

PCB Regulations (SOR/2008-273)

The *PCB Regulations* (the Regulations) set specific deadlines for ending the use of PCBs in concentrations at or above 50 mg/kg, eliminating all PCBs and equipment containing PCBs currently in storage and limiting the period of time PCBs can be stored before being destroyed. The Regulations also establish sound practices for the better management of the remaining PCBs in use (i.e. those with content of less than 50 mg/kg), until their eventual elimination, to prevent contamination of dielectric fluids and dispersion of PCBs in small quantities into other liquids.

Ozone Depleting Substances (ODSs) and Other Halocarbons

Background Information on ODSs

Within Ontario, the general use of ozone depleting substances (ODSs) and other halocarbons is controlled through Regulation 463/10 of the Environmental Protection Act. Production of ODSs in the form of hydro chlorofluorocarbons (HCFCs) and chlorofluorocarbons (CFCs) ceased in Canada in 1993 as a result of their ozone-depleting characteristics. Importation of CFCs into Canada ceased in 1997 and total ban was placed on their use since 2010. The use of these materials is still permitted in existing equipment, but equipment must be serviced by a licensed contractor such that CFCs are contained and not released to the environment during servicing or operation.

Mould & Water Damage

Mould growth inside buildings is due to excess moisture caused by leakages, condensation or capillary movement of water into the building. Toxic moulds such as *Stachybotrys chartarum* and some species of *Aspergillus* spp. are greenish-black, wet and slimy moulds that grow on soaking wet cellulose-based materials. They are often found near water leaks or where drying is very slow and can form after flooding if insufficient cleanup and drying occurred. They will generally not occur if materials are kept dry.

MPL conducted a general visual assessment for any obvious signs of visible mould and/or water damage. Based on our visual observations, the following guidelines were used in providing our recommendations for remedial action where required:

- Institute of Inspection Cleaning and Restoration Certification (IICRC) S520 Standard and Reference for Professional Mould Remediation,
- The Canadian Construction Association (CCA) Mould Guidelines for the Canadian construction industry (CCA document 82-2004)
- Environmental Abatement Council of Canada (EACC) Mould Abatement Guidelines.

Radioactive Materials

There are two types of smoke detectors commonly found in building (residential, institutional, commercial, industrial, etc.). Photoelectric-type smoke detectors detect smoke using an optical sensor, whereas ionization-type smoke detectors use an ionization chamber containing radioactive material. The ionization type is cheaper and is particularly common in older buildings. A typical modern detector contains about 1.0 microcurie of the radioactive element americium, a decrease from 3 microcurie in 1978. The use of sealed radioactive material sources in fire detection systems is still permitted and regulated by the Canadian Nuclear Safety Commission (CNSC) and the Canadian Nuclear Safety Act. The radioactive sources in smoke alarms are sealed and contained within a metal case inside the smoke detector and must not be damaged or tampered with.

Other Designated Substances

Select Designated Substances (acrylonitrile, arsenic, coke oven emissions, ethylene oxide, isocyanates, benzene, or vinyl chloride) are not expected to be present in the building in matrix or sufficient quantities to cause an exceedance of Ministry of Labour exposure guidelines. As such, no sampling was conducted for these materials.

Vinyl Chloride

Vinyl chloride (monomer) is likely to be present in stable form within poly vinyl-chloride (PVC) piping and conduits and as a component of interior finishes. Such building materials are not considered to be hazardous in their current matrix/composition.

Acrylonitrile

Acrylonitrile or ACN (also known as vinyl cyanide) is an explosive, flammable liquid used in the manufacture of acrylic fibres, rubber-like materials and pesticide fumigants. Acrylonitrile was not noted and would not be expected to be present in the project specific area/surveyed area/subject building.

Arsenic

Arsenic is used in metallurgy for hardening copper, lead and alloys, in pigment production, in the manufacture of certain types of glass, in insecticides, fungicides and rodenticides, as a by-product in the smelting of copper ores, and as a dopant material in semiconductor manufacturing. Arsenic or arsenic compounds were not noted and are not expected to be present in the project specific area/surveyed area/subject building.

Benzene

Benzene or benzol is a colourless liquid. It is used as an intermediate in the production of styrene, phenol, cyclohexane, and other organic chemicals, and in the manufacture of detergents, pesticides, solvents, and paint removers. It is also found in gasoline. Benzene may be present in stable form in roofing materials, paints and adhesives located throughout the subject building. Such building materials are not considered to be hazardous in their current matrix/composition.

Coke Oven Emissions

Coke oven emission is benzene soluble fraction of total particulate matter of the substances emitted into the atmosphere from metallurgical coke ovens.

Ethylene Oxides

Ethylene oxide is a colourless gas liquefying below 12°C. It is used generally as a fumigant and sterilizing agent for medical equipment. It is used generally as a fumigant and sterilizing agent for medical equipment.

Isocyanates

Isocyanates compounds may be present in stable form in paint finishes, varnishes, and polyurethane plastics, synthetic rubbers, foams and adhesives. Such building materials are not considered to be hazardous in their current matrix/composition.

In order to reduce the potential for exposure to workers or occupants, any suspect hazardous building material(s) that are not detailed within this survey due to inaccessibility and/or are discovered during renovation/demolition activities, must be properly assessed and/or tested prior to their disturbance.

APPENDIX C

Laboratory Analytical Reports

Certificate of Analysis

McIntosh Perry Limited (Concord)

6240 Hwy 7, Suite 200
Woodbridge, ON L4H 0R2
Attn: Atif Mohamed

Client PO:
Project: Z1920014HZ-200 LEES
Custody:

Report Date: 26-Nov-2019
Order Date: 4-Nov-2019

Revised Report

Order #: 1945297

This Certificate of Analysis contains analytical data applicable to the following samples as submitted :

| Paracel ID | Client ID |
|--------------|--|
| 1945297-01 | BS 1.1 - A02 - Mech. Rm - Unilux Machine Gasket |
| 1945297-02 | BS 1.2 - A02 - Mech. Rm - Unilux Machine Gasket |
| 1945297-03 | BS 1.3 - A02 - Mech. Rm - Unilux Machine Gasket |
| 1945297-04 | BS 2.1 - 104C - Parging Cement |
| 1945297-05 | BS 2.2 - 104C - Parging Cement |
| 1945297-06 | BS 2.3 - 104C - Parging Cement |
| 1945297-07 | BS 3.1 - A105 - Work Bench #2 - Mech. Pipe Insulation |
| 1945297-08 | BS 3.2 - A105 - Work Bench #2 - Mech. Pipe Insulation |
| 1945297-09 | BS 3.3 - A105 - Work Bench #2 - Mech. Pipe Insulation |
| 1945297-10 | BS 4.1 - A140 - Floor Levelling Compound |
| 1945297-11 | BS 4.2 - A140 - Floor Levelling Compound |
| 1945297-12 | BS 4.3 - A140 - Floor Levelling Compound |
| 1945297-13 | BS 5.1 - A139 - Plaster on Columns |
| 1945297-14 | BS 5.2 - A139 - Plaster on Columns |
| 1945297-15 | BS 5.3 - A139 - Plaster on Columns |
| 1945297-16 | BS 6.1 - A144 - High Traffic Coating |
| 1945297-17 | BS 6.2 - A144 - High Traffic Coating |
| 1945297-18 | BS 6.3 - A144 - High Traffic Coating |
| 1945297-19 | BS 7.1 - A139 - Int. Window Caulking |
| 1945297-20 | BS 7.2 - A139 - Int. Window Caulking |
| 1945297-21 | BS 7.3 - A139 - Int. Window Caulking |
| 1945297-22 | BS 8.1 - A136 - VFT (12x12) - Off White w/Gray & Black Streaks |
| 1945297-23.1 | BS 8.2 - A136 - VFT (12x12) - Off White w/Gray & Black Streaks |
| 1945297-23.2 | BS 8.2 - A136 - VFT (12x12) - Off White w/Gray & Black Streaks |
| 1945297-24.1 | BS 8.3 - A136 - VFT (12x12) - Off White w/Gray & Black Streaks |
| 1945297-24.2 | BS 8.3 - A136 - VFT (12x12) - Off White w/Gray & Black Streaks |

Approved By:



Emma Diaz
Senior Analyst

Any use of these results implies your agreement that our total liability in connection with this work, however arising, shall be limited to the amount paid by you for this work, and that our employees or agents shall not under any circumstances be liable to you in connection with this work.

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

| | |
|--------------|--|
| 1945297-25 | BS 9.1 - A138E - VFT (12x12) - Beige w/Brown & Grey Flakes |
| 1945297-26 | BS 9.2 - A138E - VFT (12x12) - Beige w/Brown & Grey Flakes |
| 1945297-27.1 | BS 9.3 - A138E - VFT (12x12) - Beige w/Brown & Grey Flakes |
| 1945297-27.2 | BS 9.3 - A138E - VFT (12x12) - Beige w/Brown & Grey Flakes |
| 1945297-28 | BS 10.1 - A122B - VFT (12x12) - Olive Green w/Grey Flakes |
| 1945297-29 | BS 10.2 - A122B - VFT (12x12) - Olive Green w/Grey Flakes |
| 1945297-30 | BS 10.3 - A122B - VFT (12x12) - Olive Green w/Grey Flakes |
| 1945297-31.1 | BS 11.1 - A127-Archives RM-VFT(12x12)-Grey w/Blue Streaks |
| 1945297-31.2 | BS 11.1 - A127-Archives RM-VFT(12x12)-Grey w/Blue Streaks |
| 1945297-32.1 | BS 11.2 - A127-Archives RM-VFT(12x12)-Grey w/Blue Streaks |
| 1945297-32.2 | BS 11.2 - A127-Archives RM-VFT(12x12)-Grey w/Blue Streaks |
| 1945297-33.1 | BS 11.3 - A127-Archives RM-VFT(12x12)-Grey w/Blue Streaks |
| 1945297-33.2 | BS 11.3 - A127-Archives RM-VFT(12x12)-Grey w/Blue Streaks |
| 1945297-34.1 | BS 12.1 - A122B - VFT (12x12) - Off White w/Brown Flakes |
| 1945297-34.2 | BS 12.1 - A122B - VFT (12x12) - Off White w/Brown Flakes |
| 1945297-35.1 | BS 12.2 - A122B - VFT (12x12) - Off White w/Brown Flakes |
| 1945297-35.2 | BS 12.2 - A122B - VFT (12x12) - Off White w/Brown Flakes |
| 1945297-36.1 | BS 12.3 - A122B - VFT (12x12) - Off White w/Brown Flakes |
| 1945297-36.2 | BS 12.3 - A122B - VFT (12x12) - Off White w/Brown Flakes |
| 1945297-37 | BS 13.1 - A142 - Concrete Block Mortar |
| 1945297-38 | BS 13.2 - A142 - Concrete Block Mortar |
| 1945297-39 | BS 13.3 - A142 - Concrete Block Mortar |
| 1945297-40 | BS 14.1 - A106C - Wall Tile Grout |
| 1945297-41 | BS 14.2 - A106C - Wall Tile Grout |
| 1945297-42 | BS 14.3 - A106C - Wall Tile Grout |
| 1945297-43 | BS 15.1 - A139 - Wall Texture Coating |
| 1945297-44 | BS 15.2 - A139 - Wall Texture Coating |
| 1945297-45 | BS 15.3 - A139 - Wall Texture Coating |
| 1945297-46 | BS 15.4 - A139 - Wall Texture Coating |
| 1945297-47 | BS 15.5 - A140 - Wall Texture Coating |
| 1945297-48 | BS 15.6 - A140 - Wall Texture Coating |
| 1945297-49 | BS 15.7 - A140 - Wall Texture Coating |
| 1945297-50 | BS 16.1 - A136-2x4-SCT-Fissures |
| 1945297-51 | BS 16.2 - A136-2x4-SCT-Fissures |
| 1945297-52 | BS 16.3 - A136-2x4-SCT-Fissures |
| 1945297-53 | BS 17.1 - A106 - 2x4 - SCT - Pinholes with Large Fissures |
| 1945297-54 | BS 17.2 - A100B - 2x4 - SCT - Pinholes with Large Fissures |
| 1945297-55 | BS 17.3 - A127C - 2x4 - SCT - Pinholes with Large Fissures |
| 1945297-56 | BS 18.1 - A106C - 12x12 - Red w/Flakes |
| 1945297-57.1 | BS 18.2 - A106C - 12x12 - Red w/Flakes |
| 1945297-57.2 | BS 18.2 - A106C - 12x12 - Red w/Flakes |
| 1945297-58.1 | BS 18.3 - A106C - 12x12 - Red w/Flakes |
| 1945297-58.2 | BS 18.3 - A106C - 12x12 - Red w/Flakes |
| 1945297-59 | BS 19.1 - D202B-Carpet Mastic |

Certificate of Analysis

Report Date: 26-Nov-2019

Client: **McIntosh Perry Limited (Concord)**

Order Date: 4-Nov-2019

Client PO:

Project Description: **Z1920014HZ-200 LEES**

| | |
|--------------|--|
| 1945297-60 | BS 19.2 - D202B-Carpet Mastic |
| 1945297-61 | BS 19.3 - D202B-Carpet Mastic |
| 1945297-62 | BS 20.1 - BS215E - VFT 2x2 - Off White w/Blue Streaks |
| 1945297-63 | BS 20.2 - BS215E - VFT 2x2 - Off White w/Blue Streaks |
| 1945297-64 | BS 20.3 - BS215E - VFT 2x2 - Off White w/Blue Streaks |
| 1945297-65 | BS 21.1- B215N - Plaster on Beam |
| 1945297-66 | BS 21.2- B215N - Plaster on Beam |
| 1945297-67 | BS 21.3- B215N - Plaster on Beam |
| 1945297-68.1 | BS 22.1 - C209 - VFT 12x12 - Off White w/Grey & Black Flakes |
| 1945297-68.2 | BS 22.1 - C209 - VFT 12x12 - Off White w/Grey & Black Flakes |
| 1945297-69.1 | BS 22.2 - C209 - VFT 12x12 - Off White w/Grey & Black Flakes |
| 1945297-69.2 | BS 22.2 - C209 - VFT 12x12 - Off White w/Grey & Black Flakes |
| 1945297-70.1 | BS 22.3 - C209 - VFT 12x12 - Off White w/Grey & Black Flakes |
| 1945297-70.2 | BS 22.3 - C209 - VFT 12x12 - Off White w/Grey & Black Flakes |
| 1945297-71.1 | BS 23.1 - C209 - VFT 12x12 - Beige w/Multicolor Flakes |
| 1945297-71.2 | BS 23.1 - C209 - VFT 12x12 - Beige w/Multicolor Flakes |
| 1945297-72.1 | BS 23.2 - C209 - VFT 12x12 - Beige w/Multicolor Flakes |
| 1945297-72.2 | BS 23.2 - C209 - VFT 12x12 - Beige w/Multicolor Flakes |
| 1945297-73.1 | BS 23.3 - C209 - VFT 12x12 - Beige w/Multicolor Flakes |
| 1945297-73.2 | BS 23.3 - C209 - VFT 12x12 - Beige w/Multicolor Flakes |
| 1945297-74.1 | BS 24.1 - C200 Hallway - VFT 12x12 - Off White w/Grey Flakes |
| 1945297-74.2 | BS 24.1 - C200 Hallway - VFT 12x12 - Off White w/Grey Flakes |
| 1945297-75.1 | BS 24.2 - C200 Hallway - VFT 12x12 - Off White w/Grey Flakes |
| 1945297-75.2 | BS 24.2 - C200 Hallway - VFT 12x12 - Off White w/Grey Flakes |
| 1945297-76.1 | BS 24.3 - C144 Hallway - VFT 12x12 - Off White w/Grey Flakes |
| 1945297-76.2 | BS 24.3 - C144 Hallway - VFT 12x12 - Off White w/Grey Flakes |
| 1945297-77.1 | BS 25.1 - C115 - VFT 12x12 - Pink w/Dots |
| 1945297-77.2 | BS 25.1 - C115 - VFT 12x12 - Pink w/Dots |
| 1945297-78.1 | BS 25.2 - C115 - VFT 12x12 - Pink w/Dots |
| 1945297-78.2 | BS 25.2 - C115 - VFT 12x12 - Pink w/Dots |
| 1945297-79.1 | BS 25.3 - C115 - VFT 12x12 - Pink w/Dots |
| 1945297-79.2 | BS 25.3 - C115 - VFT 12x12 - Pink w/Dots |
| 1945297-80.1 | BS 26.1 - E041 - VFT 12x12 - Off White w/Blue Streaks |
| 1945297-80.2 | BS 26.1 - E041 - VFT 12x12 - Off White w/Blue Streaks |
| 1945297-81.1 | BS 26.2 - E041 - VFT 12x12 - Off White w/Blue Streaks |
| 1945297-81.2 | BS 26.2 - E041 - VFT 12x12 - Off White w/Blue Streaks |
| 1945297-82.1 | BS 26.3 - E041 - VFT 12x12 - Off White w/Blue Streaks |
| 1945297-82.2 | BS 26.3 - E041 - VFT 12x12 - Off White w/Blue Streaks |
| 1945297-83.1 | BS 27.1 - E053 - VFT 12x12 - Grey w/White & Light Grey Streaks |
| 1945297-83.2 | BS 27.1 - E053 - VFT 12x12 - Grey w/White & Light Grey Streaks |
| 1945297-84.1 | BS 27.2 - E053 - VFT 12x12 - Grey w/White & Light Grey Streaks |
| 1945297-84.2 | BS 27.2 - E053 - VFT 12x12 - Grey w/White & Light Grey Streaks |
| 1945297-85.1 | BS 27.3 - E053 - VFT 12x12 - Grey w/White & Light Grey Streaks |
| 1945297-85.2 | BS 27.3 - E053 - VFT 12x12 - Grey w/White & Light Grey Streaks |

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

| | |
|--------------|--|
| 1945297-86.1 | BS 28.1 - E244 - VFT 12x12 - Off White w/ Grey Streaks |
| 1945297-86.2 | BS 28.1 - E244 - VFT 12x12 - Off White w/ Grey Streaks |
| 1945297-87.1 | BS 28.2 - E244 - VFT 12x12 - Off White w/ Grey Streaks |
| 1945297-87.2 | BS 28.2 - E244 - VFT 12x12 - Off White w/ Grey Streaks |
| 1945297-88.1 | BS 28.3 - E244 - VFT 12x12 - Off White w/ Grey Streaks |
| 1945297-88.2 | BS 28.3 - E244 - VFT 12x12 - Off White w/ Grey Streaks |
| 1945297-89 | BS 29.1 - D108 - Men's Change Rm - 12x12 - ACT |
| 1945297-90 | BS 29.2 - D108 - Men's Change Rm - 12x12 - ACT |
| 1945297-91 | BS 29.3 - D108 - Men's Change Rm - 12x12 - ACT |
| 1945297-92.1 | BS 30.1 - D108 - Ceiling Mastic (Pucks) |
| 1945297-92.2 | BS 30.1 - D108 - Ceiling Mastic (Pucks) |
| 1945297-93.1 | BS 30.2 - D108 - Ceiling Mastic (Pucks) |
| 1945297-93.2 | BS 30.2 - D108 - Ceiling Mastic (Pucks) |
| 1945297-94.1 | BS 30.3 - D108 - Ceiling Mastic (Pucks) |
| 1945297-94.2 | BS 30.3 - D108 - Ceiling Mastic (Pucks) |
| 1945297-95 | BS 31.1 - D108 - Ceiling Plaster |
| 1945297-96 | BS 31.2 - D108 - Ceiling Plaster |
| 1945297-97 | BS 31.3 - D108 - Ceiling Plaster |
| 1945297-98 | BS 32.1 - B100 Hallway - Sprayed Insulation |
| 1945297-99 | BS 32.2 - C141C - Tele Rm - Sprayed Insulation |
| 1945297-AA | BS 32.3 - C141C - Tele Rm - Sprayed Insulation |
| 1945297-AB | BS 32.4 - C201 - Sprayed Insulation |
| 1945297-AC | BS 32.5 - C204 - Sprayed Insulation |
| 1945297-AD | BS 33.1 - A136 - Drywall Joint Compound DJC |
| 1945297-AE | BS 33.2 - A139A - Drywall Joint Compound DJC |
| 1945297-AF | BS 33.3 - C115 - Drywall Joint Compound DJC |
| 1945297-AG | BS 33.4 - B215 - Drywall Joint Compound DJC |
| 1945297-AH | BS 33.5 - C200 Hallway - Drywall Joint Compound DJC |
| 1945297-AI | BS 33.6 - E126 - Drywall Joint Compound DJC |
| 1945297-AJ | BS 33.7 - E053 - Drywall Joint Compound DJC |
| 1945297-AK | BS 34.1 - E038 - Mech. Rm - DJC |
| 1945297-AL | BS 34.2 - E038 - Mech. Rm - DJC |
| 1945297-AM | BS 34.3 - E038 - Mech. Rm - DJC |
| 1945297-AN.1 | BS 35.1- C115 - VFT 12x12 - Off White w/Dots |
| 1945297-AN.2 | BS 35.1- C115 - VFT 12x12 - Off White w/Dots |
| 1945297-AO.1 | BS 35.2- C115 - VFT 12x12 - Off White w/Dots |
| 1945297-AO.2 | BS 35.2- C115 - VFT 12x12 - Off White w/Dots |
| 1945297-AP.1 | BS 35.3- C115 - VFT 12x12 - Off White w/Dots |
| 1945297-AP.2 | BS 35.3- C115 - VFT 12x12 - Off White w/Dots |

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

Asbestos, PLM Visual Estimation **MDL - 0.5%**

| Parcel ID | Sample Date | Colour | Description | Asbestos Detected | Material Identification | % Content |
|------------|-------------|-------------|--------------------------|-------------------|---|-----------|
| 1945297-01 | 30-Sep-19 | Beige | Gasket | Yes | Client ID: BS 1.1 - A02 - Mech. Rm - Unilux Machine Gasket | |
| | | | | | Chrysotile | 65 |
| | | | | | Non-Fibers | 35 |
| 1945297-02 | 30-Sep-19 | | | | Client ID: BS 1.2 - A02 - Mech. Rm - Unilux Machine Gasket | |
| | | | | | not analyzed | |
| 1945297-03 | 30-Sep-19 | | | | Client ID: BS 1.3 - A02 - Mech. Rm - Unilux Machine Gasket | |
| | | | | | not analyzed | |
| 1945297-04 | 30-Sep-19 | Grey | Parging | Yes | Client ID: BS 2.1 - 104C - Parging Cement | |
| | | | | | Chrysotile | 60 |
| | | | | | Non-Fibers | 40 |
| 1945297-05 | 30-Sep-19 | | | | Client ID: BS 2.2 - 104C - Parging Cement | |
| | | | | | not analyzed | |
| 1945297-06 | 30-Sep-19 | | | | Client ID: BS 2.3 - 104C - Parging Cement | |
| | | | | | not analyzed | |
| 1945297-07 | 30-Sep-19 | Brown | Pipe Insulation | Yes | Client ID: BS 3.1 - A105 - Work Bench #2 - Mech. Pipe Insulation | |
| | | | | | Chrysotile | 10 |
| | | | | | Non-Fibers | 90 |
| 1945297-08 | 30-Sep-19 | | | | Client ID: BS 3.2 - A105 - Work Bench #2 - Mech. Pipe Insulation | |
| | | | | | not analyzed | |
| 1945297-09 | 30-Sep-19 | | | | Client ID: BS 3.3 - A105 - Work Bench #2 - Mech. Pipe Insulation | |
| | | | | | not analyzed | |
| 1945297-10 | 30-Sep-19 | Brown/Black | Leveling Compound/Mastic | No | Client ID: BS 4.1 - A140 - Floor Levelling Compound | [Z-01] |
| | | | | | Non-Fibers | 97 |
| | | | | | Other fibers | 3 |

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

Asbestos, PLM Visual Estimation **MDL - 0.5%**

| Parcel ID | Sample Date | Colour | Description | Asbestos Detected | Material Identification | % Content |
|------------|-------------|-------------|--------------------------|-------------------|--|-----------|
| 1945297-11 | 30-Sep-19 | Brown/Black | Leveling Compound/Mastic | No | Client ID: BS 4.2 - A140 - Floor Levelling Compound | [Z-01] |
| | | | | | Non-Fibers | 97 |
| | | | | | Other fibers | 3 |
| 1945297-12 | 30-Sep-19 | Brown/Black | Leveling Compound/Mastic | No | Client ID: BS 4.3 - A140 - Floor Levelling Compound | [Z-01] |
| | | | | | Non-Fibers | 97 |
| | | | | | Other fibers | 3 |
| 1945297-13 | 30-Sep-19 | Grey | Plaster | No | Client ID: BS 5.1 - A139 - Plaster on Columns | |
| | | | | | Non-Fibers | 100 |
| 1945297-14 | 30-Sep-19 | Grey | Plaster | No | Client ID: BS 5.2 - A139 - Plaster on Columns | |
| | | | | | Non-Fibers | 100 |
| 1945297-15 | 30-Sep-19 | Grey | Plaster | No | Client ID: BS 5.3 - A139 - Plaster on Columns | |
| | | | | | Non-Fibers | 100 |
| 1945297-16 | 30-Sep-19 | Beige | Coating | No | Client ID: BS 6.1 - A144 - High Traffic Coating | |
| | | | | | Non-Fibers | 100 |
| 1945297-17 | 30-Sep-19 | Beige | Coating | No | Client ID: BS 6.2 - A144 - High Traffic Coating | |
| | | | | | Non-Fibers | 100 |
| 1945297-18 | 30-Sep-19 | Beige | Coating | No | Client ID: BS 6.3 - A144 - High Traffic Coating | |
| | | | | | Non-Fibers | 100 |
| 1945297-19 | 30-Sep-19 | Black | Caulking | Yes | Client ID: BS 7.1 - A139 - Int. Window Caulking | |
| | | | | | Chrysotile | 2 |
| | | | | | Non-Fibers | 93 |
| | | | | | Other fibers | 5 |
| 1945297-20 | 30-Sep-19 | | | | Client ID: BS 7.2 - A139 - Int. Window Caulking | |
| | | | | | not analyzed | |

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

Asbestos, PLM Visual Estimation **MDL - 0.5%**

| Parcel ID | Sample Date | Colour | Description | Asbestos Detected | Material Identification | % Content |
|--------------|-------------|-------------|------------------|-------------------|---|-----------|
| 1945297-21 | 30-Sep-19 | | | | Client ID: BS 7.3 - A139 - Int. Window Caulking | |
| | | | | | not analyzed | |
| 1945297-22 | 30-Sep-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 8.1 - A136 - VFT (12x12) - Off White w/Gray & Black Streaks | [Z-01c] |
| | | | | | Non-Fibers | 100 |
| 1945297-23.1 | 30-Sep-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 8.2 - A136 - VFT (12x12) - Off White w/Gray & Black Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-23.2 | 30-Sep-19 | | | | Client ID: BS 8.2 - A136 - VFT (12x12) - Off White w/Gray & Black Streaks | [Z-01a] |
| | | | | | not analyzed | |
| 1945297-24.1 | 30-Sep-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 8.3 - A136 - VFT (12x12) - Off White w/Gray & Black Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-24.2 | 30-Sep-19 | | | | Client ID: BS 8.3 - A136 - VFT (12x12) - Off White w/Gray & Black Streaks | [Z-01a] |
| | | | | | not analyzed | |
| 1945297-25 | 01-Oct-19 | Beige | Vinyl Floor Tile | No | Client ID: BS 9.1 - A138E - VFT (12x12) - Beige w/Brown & Grey Flakes | [Z-01b] |
| | | | | | Non-Fibers | 100 |
| 1945297-26 | 01-Oct-19 | Beige | Vinyl Floor Tile | No | Client ID: BS 9.2 - A138E - VFT (12x12) - Beige w/Brown & Grey Flakes | [Z-01b] |
| | | | | | Non-Fibers | 100 |
| 1945297-27.1 | 01-Oct-19 | Beige | Vinyl Floor Tile | No | Client ID: BS 9.3 - A138E - VFT (12x12) - Beige w/Brown & Grey Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-27.2 | 01-Oct-19 | Black | Mastic | No | Client ID: BS 9.3 - A138E - VFT (12x12) - Beige w/Brown & Grey Flakes | |
| | | | | | Cellulose | 3 |
| | | | | | Non-Fibers | 97 |
| 1945297-28 | 01-Oct-19 | Olive green | Vinyl Floor Tile | No | Client ID: BS 10.1 - A122B - VFT (12x12) - Olive Green w/Grey Flakes | [Z-01c] |
| | | | | | Non-Fibers | 100 |
| 1945297-29 | 01-Oct-19 | Olive green | Vinyl Floor Tile | No | Client ID: BS 10.2 - A122B - VFT (12x12) - Olive Green w/Grey Flakes | [Z-01c] |
| | | | | | Non-Fibers | 100 |

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

Asbestos, PLM Visual Estimation **MDL - 0.5%**

| Parcel ID | Sample Date | Colour | Description | Asbestos Detected | Material Identification | % Content |
|--------------|-------------|-------------|------------------|-------------------|--|-----------|
| 1945297-30 | 01-Oct-19 | Olive green | Vinyl Floor Tile | No | Client ID: BS 10.3 - A122B - VFT (12x12) - Olive Green w/Grey Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-31.1 | 01-Oct-19 | Grey | Vinyl Floor Tile | No | Client ID: BS 11.1 - A127-Archives RM-VFT(12x12)-Grey w/Blue Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-31.2 | 01-Oct-19 | | | | Client ID: BS 11.1 - A127-Archives RM-VFT(12x12)-Grey w/Blue Streaks | [Z-01a] |
| | | | | | not analyzed | |
| 1945297-32.1 | 01-Oct-19 | Grey | Vinyl Floor Tile | No | Client ID: BS 11.2 - A127-Archives RM-VFT(12x12)-Grey w/Blue Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-32.2 | 01-Oct-19 | Black | Mastic | No | Client ID: BS 11.2 - A127-Archives RM-VFT(12x12)-Grey w/Blue Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-33.1 | 01-Oct-19 | Grey | Vinyl Floor Tile | No | Client ID: BS 11.3 - A127-Archives RM-VFT(12x12)-Grey w/Blue Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-33.2 | 01-Oct-19 | | | | Client ID: BS 11.3 - A127-Archives RM-VFT(12x12)-Grey w/Blue Streaks | [Z-01a] |
| | | | | | not analyzed | |
| 1945297-34.1 | 01-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 12.1 - A122B - VFT (12x12) - Off White w/Brown Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-34.2 | 01-Oct-19 | | | | Client ID: BS 12.1 - A122B - VFT (12x12) - Off White w/Brown Flakes | [Z-01a] |
| | | | | | not analyzed | |
| 1945297-35.1 | 01-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 12.2 - A122B - VFT (12x12) - Off White w/Brown Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-35.2 | 01-Oct-19 | | | | Client ID: BS 12.2 - A122B - VFT (12x12) - Off White w/Brown Flakes | [Z-01a] |
| | | | | | not analyzed | |
| 1945297-36.1 | 01-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 12.3 - A122B - VFT (12x12) - Off White w/Brown Flakes | |
| | | | | | Non-Fibers | 100 |

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

Asbestos, PLM Visual Estimation **MDL - 0.5%**

| Parcel ID | Sample Date | Colour | Description | Asbestos Detected | Material Identification | % Content |
|--------------|-------------|--------|--------------|-------------------|---|----------------|
| 1945297-36.2 | 01-Oct-19 | | | | Client ID: BS 12.3 - A122B - VFT (12x12) - Off White w/Brown Flakes not analyzed | [Z-01a] |
| 1945297-37 | 01-Oct-19 | Grey | Mortar | No | Client ID: BS 13.1 - A142 - Concrete Block Mortar | Non-Fibers 100 |
| 1945297-38 | 01-Oct-19 | Grey | Mortar | No | Client ID: BS 13.2 - A142 - Concrete Block Mortar | Non-Fibers 100 |
| 1945297-39 | 01-Oct-19 | Grey | Mortar | No | Client ID: BS 13.3 - A142 - Concrete Block Mortar | Non-Fibers 100 |
| 1945297-40 | 01-Oct-19 | Grey | Grout | No | Client ID: BS 14.1 - A106C - Wall Tile Grout | Non-Fibers 100 |
| 1945297-41 | 01-Oct-19 | White | Grout | No | Client ID: BS 14.2 - A106C - Wall Tile Grout | Non-Fibers 100 |
| 1945297-42 | 01-Oct-19 | White | Grout | No | Client ID: BS 14.3 - A106C - Wall Tile Grout | Non-Fibers 100 |
| 1945297-43 | 01-Oct-19 | Grey | Texture Coat | No | Client ID: BS 15.1 - A139 - Wall Texture Coating | Non-Fibers 100 |
| 1945297-44 | 01-Oct-19 | Grey | Texture Coat | No | Client ID: BS 15.2 - A139 - Wall Texture Coating | Non-Fibers 100 |
| 1945297-45 | 01-Oct-19 | Grey | Texture Coat | No | Client ID: BS 15.3 - A139 - Wall Texture Coating | Non-Fibers 100 |
| 1945297-46 | 01-Oct-19 | Grey | Texture Coat | No | Client ID: BS 15.4 - A139 - Wall Texture Coating | Non-Fibers 100 |
| 1945297-47 | 01-Oct-19 | White | Texture Coat | No | Client ID: BS 15.5 - A140 - Wall Texture Coating | Non-Fibers 100 |

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

Asbestos, PLM Visual Estimation **MDL - 0.5%**

| Parcel ID | Sample Date | Colour | Description | Asbestos Detected | Material Identification | % Content |
|------------|-------------|--------|------------------|-------------------|--|-----------|
| 1945297-48 | 01-Oct-19 | White | Texture Coat | No | Client ID: BS 15.6 - A140 - Wall Texture Coating | |
| | | | | | Non-Fibers | 100 |
| 1945297-49 | 01-Oct-19 | White | Texture Coat | No | Client ID: BS 15.7 - A140 - Wall Texture Coating | |
| | | | | | Non-Fibers | 100 |
| 1945297-50 | 01-Oct-19 | Brown | Ceiling Tile | No | Client ID: BS 16.1 - A136-2x4-SCT-Fissures | |
| | | | | | Cellulose | 95 |
| | | | | | Non-Fibers | 5 |
| 1945297-51 | 01-Oct-19 | Brown | Ceiling Tile | No | Client ID: BS 16.2 - A136-2x4-SCT-Fissures | |
| | | | | | Cellulose | 95 |
| | | | | | Non-Fibers | 5 |
| 1945297-52 | 01-Oct-19 | Brown | Ceiling Tile | No | Client ID: BS 16.3 - A136-2x4-SCT-Fissures | |
| | | | | | Cellulose | 95 |
| | | | | | Non-Fibers | 5 |
| 1945297-53 | 01-Oct-19 | Grey | Ceiling Tile | No | Client ID: BS 17.1 - A106 - 2x4 - SCT - Pinholes with Large Fissures | |
| | | | | | Cellulose | 40 |
| | | | | | MMVF | 30 |
| | | | | | Non-Fibers | 30 |
| 1945297-54 | 01-Oct-19 | Grey | Ceiling Tile | No | Client ID: BS 17.2 - A100B - 2x4 - SCT - Pinholes with Large Fissures | |
| | | | | | Cellulose | 40 |
| | | | | | MMVF | 30 |
| | | | | | Non-Fibers | 30 |
| 1945297-55 | 01-Oct-19 | Grey | Ceiling Tile | No | Client ID: BS 17.3 - A127C - 2x4 - SCT - Pinholes with Large Fissures | |
| | | | | | Cellulose | 40 |
| | | | | | MMVF | 30 |
| | | | | | Non-Fibers | 30 |
| 1945297-56 | 01-Oct-19 | Red | Vinyl Floor Tile | No | Client ID: BS 18.1 - A106C - 12x12 - Red w/Flakes | |
| | | | | | Non-Fibers | 100 |

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

Asbestos, PLM Visual Estimation **MDL - 0.5%**

| Parcel ID | Sample Date | Colour | Description | Asbestos Detected | Material Identification | % Content |
|--------------|-------------|-----------|------------------|-------------------|--|-----------|
| 1945297-57.1 | 01-Oct-19 | Red | Vinyl Floor Tile | No | Client ID: BS 18.2 - A106C - 12x12 - Red w/Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-57.2 | 01-Oct-19 | Black | Mastic | No | Client ID: BS 18.2 - A106C - 12x12 - Red w/Flakes | |
| | | | | | [Z-01a] | |
| | | | | | Non-Fibers | 100 |
| 1945297-58.1 | 01-Oct-19 | Red | Vinyl Floor Tile | No | Client ID: BS 18.3 - A106C - 12x12 - Red w/Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-58.2 | 01-Oct-19 | | | | Client ID: BS 18.3 - A106C - 12x12 - Red w/Flakes | |
| | | | | | [Z-01a] | |
| | | | | | not analyzed | |
| 1945297-59 | 01-Oct-19 | Brown | Mastic | No | Client ID: BS 19.1 - D202B-Carpet Mastic | |
| | | | | | Non-Fibers | 100 |
| 1945297-60 | 01-Oct-19 | Brown | Mastic | No | Client ID: BS 19.2 - D202B-Carpet Mastic | |
| | | | | | Non-Fibers | 100 |
| 1945297-61 | 01-Oct-19 | Brown | Mastic | No | Client ID: BS 19.3 - D202B-Carpet Mastic | |
| | | | | | Non-Fibers | 100 |
| 1945297-62 | 01-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 20.1 - BS215E - VFT 2x2 - Off White w/Blue Streaks | |
| | | | | | [Z-01c] | |
| | | | | | Non-Fibers | 100 |
| 1945297-63 | 01-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 20.2 - BS215E - VFT 2x2 - Off White w/Blue Streaks | |
| | | | | | [Z-01c] | |
| | | | | | Non-Fibers | 100 |
| 1945297-64 | 01-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 20.3 - BS215E - VFT 2x2 - Off White w/Blue Streaks | |
| | | | | | [Z-01c] | |
| | | | | | Non-Fibers | 100 |
| 1945297-65 | 01-Oct-19 | Grey | Plaster | No | Client ID: BS 21.1- B215N - Plaster on Beam | |
| | | | | | [Z-01f] | |
| | | | | | Non-Fibers | 100 |
| 1945297-66 | 01-Oct-19 | Grey | Plaster | Yes | Client ID: BS 21.2- B215N - Plaster on Beam | |
| | | | | | [Z-01f] | |
| | | | | | Tremolite | 1 |
| | | | | | Non-Fibers | 99 |

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

Asbestos, PLM Visual Estimation **MDL - 0.5%**

| Parcel ID | Sample Date | Colour | Description | Asbestos Detected | Material Identification | % Content |
|--------------|-------------|-----------|------------------|-------------------|---|-----------|
| 1945297-67 | 01-Oct-19 | Grey | Plaster | No | Client ID: BS 21.3- B215N - Plaster on Beam | [Z-01f] |
| | | | | | Non-Fibers | 100 |
| 1945297-68.1 | 01-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 22.1 - C209 - VFT 12x12 - Off White w/Grey & Black Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-68.2 | 01-Oct-19 | Black | Mastic | No | Client ID: BS 22.1 - C209 - VFT 12x12 - Off White w/Grey & Black Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-69.1 | 01-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 22.2 - C209 - VFT 12x12 - Off White w/Grey & Black Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-69.2 | 01-Oct-19 | Black | Mastic | No | Client ID: BS 22.2 - C209 - VFT 12x12 - Off White w/Grey & Black Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-70.1 | 01-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 22.3 - C209 - VFT 12x12 - Off White w/Grey & Black Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-70.2 | 01-Oct-19 | Black | Mastic | No | Client ID: BS 22.3 - C209 - VFT 12x12 - Off White w/Grey & Black Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-71.1 | 01-Oct-19 | Beige | Vinyl Floor Tile | No | Client ID: BS 23.1 - C209 - VFT 12x12 - Beige w/Multicolor Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-71.2 | 01-Oct-19 | Black | Mastic | No | Client ID: BS 23.1 - C209 - VFT 12x12 - Beige w/Multicolor Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-72.1 | 01-Oct-19 | Beige | Vinyl Floor Tile | No | Client ID: BS 23.2 - C209 - VFT 12x12 - Beige w/Multicolor Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-72.2 | 01-Oct-19 | Black | Mastic | No | Client ID: BS 23.2 - C209 - VFT 12x12 - Beige w/Multicolor Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-73.1 | 01-Oct-19 | Beige | Vinyl Floor Tile | No | Client ID: BS 23.3 - C209 - VFT 12x12 - Beige w/Multicolor Flakes | |
| | | | | | Non-Fibers | 100 |

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

Asbestos, PLM Visual Estimation **MDL - 0.5%**

| Parcel ID | Sample Date | Colour | Description | Asbestos Detected | Material Identification | % Content |
|--------------|-------------|-----------|------------------|-------------------|---|-----------|
| 1945297-73.2 | 01-Oct-19 | Black | Mastic | No | Client ID: BS 23.3 - C209 - VFT 12x12 - Beige w/Multicolor Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-74.1 | 02-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 24.1 - C200 Hallway - VFT 12x12 - Off White w/Grey Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-74.2 | 02-Oct-19 | Black | Mastic | No | Client ID: BS 24.1 - C200 Hallway - VFT 12x12 - Off White w/Grey Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-75.1 | 02-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 24.2 - C200 Hallway - VFT 12x12 - Off White w/Grey Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-75.2 | 02-Oct-19 | Black | Mastic | No | Client ID: BS 24.2 - C200 Hallway - VFT 12x12 - Off White w/Grey Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-76.1 | 02-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 24.3 - C144 Hallway - VFT 12x12 - Off White w/Grey Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-76.2 | 02-Oct-19 | Black | Mastic | No | Client ID: BS 24.3 - C144 Hallway - VFT 12x12 - Off White w/Grey Flakes | |
| | | | | | Non-Fibers | 100 |
| 1945297-77.1 | 02-Oct-19 | Pink | Vinyl Floor Tile | No | Client ID: BS 25.1 - C115 - VFT 12x12 - Pink w/Dots | |
| | | | | | Non-Fibers | 100 |
| 1945297-77.2 | 02-Oct-19 | | | | Client ID: BS 25.1 - C115 - VFT 12x12 - Pink w/Dots | |
| | | | | | [Z-01a] not analyzed | |
| 1945297-78.1 | 02-Oct-19 | Pink | Vinyl Floor Tile | No | Client ID: BS 25.2 - C115 - VFT 12x12 - Pink w/Dots | |
| | | | | | Non-Fibers | 100 |
| 1945297-78.2 | 02-Oct-19 | Black | Mastic | No | Client ID: BS 25.2 - C115 - VFT 12x12 - Pink w/Dots | |
| | | | | | Non-Fibers | 100 |
| 1945297-79.1 | 02-Oct-19 | Pink | Vinyl Floor Tile | No | Client ID: BS 25.3 - C115 - VFT 12x12 - Pink w/Dots | |
| | | | | | Non-Fibers | 100 |

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

Asbestos, PLM Visual Estimation **MDL - 0.5%**

| Parcel ID | Sample Date | Colour | Description | Asbestos Detected | Material Identification | % Content |
|--------------|-------------|-----------|------------------|-------------------|---|-----------|
| 1945297-79.2 | 02-Oct-19 | Black | Mastic | No | Client ID: BS 25.3 - C115 - VFT 12x12 - Pink w/Dots | |
| | | | | | Non-Fibers | 100 |
| 1945297-80.1 | 02-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 26.1 - E041 - VFT 12x12 - Off White w/Blue Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-80.2 | 02-Oct-19 | Yellow | Mastic | No | Client ID: BS 26.1 - E041 - VFT 12x12 - Off White w/Blue Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-81.1 | 02-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 26.2 - E041 - VFT 12x12 - Off White w/Blue Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-81.2 | 02-Oct-19 | | | | Client ID: BS 26.2 - E041 - VFT 12x12 - Off White w/Blue Streaks | [Z-01a] |
| | | | | | not analyzed | |
| 1945297-82.1 | 02-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 26.3 - E041 - VFT 12x12 - Off White w/Blue Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-82.2 | 02-Oct-19 | Yellow | Mastic | No | Client ID: BS 26.3 - E041 - VFT 12x12 - Off White w/Blue Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-83.1 | 02-Oct-19 | Grey | Vinyl Floor Tile | No | Client ID: BS 27.1 - E053 - VFT 12x12 - Grey w/White & Light Grey Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-83.2 | 02-Oct-19 | Yellow | Mastic | No | Client ID: BS 27.1 - E053 - VFT 12x12 - Grey w/White & Light Grey Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-84.1 | 02-Oct-19 | Grey | Vinyl Floor Tile | No | Client ID: BS 27.2 - E053 - VFT 12x12 - Grey w/White & Light Grey Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-84.2 | 02-Oct-19 | Yellow | Mastic | No | Client ID: BS 27.2 - E053 - VFT 12x12 - Grey w/White & Light Grey Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-85.1 | 02-Oct-19 | Grey | Vinyl Floor Tile | No | Client ID: BS 27.3 - E053 - VFT 12x12 - Grey w/White & Light Grey Streaks | |
| | | | | | Non-Fibers | 100 |

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

Asbestos, PLM Visual Estimation **MDL - 0.5%**

| Parcel ID | Sample Date | Colour | Description | Asbestos Detected | Material Identification | % Content |
|--------------|-------------|-----------|------------------|-------------------|---|-----------|
| 1945297-85.2 | 02-Oct-19 | Yellow | Mastic | No | Client ID: BS 27.3 - E053 - VFT 12x12 - Grey w/White & Light Grey Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-86.1 | 02-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 28.1 - E244 - VFT 12x12 - Off White w/ Grey Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-86.2 | 02-Oct-19 | | | | Client ID: BS 28.1 - E244 - VFT 12x12 - Off White w/ Grey Streaks [Z-01a] | |
| | | | | | not analyzed | |
| 1945297-87.1 | 02-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 28.2 - E244 - VFT 12x12 - Off White w/ Grey Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-87.2 | 02-Oct-19 | Black | Mastic | No | Client ID: BS 28.2 - E244 - VFT 12x12 - Off White w/ Grey Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-88.1 | 02-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 28.3 - E244 - VFT 12x12 - Off White w/ Grey Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-88.2 | 02-Oct-19 | Black | Mastic | No | Client ID: BS 28.3 - E244 - VFT 12x12 - Off White w/ Grey Streaks | |
| | | | | | Non-Fibers | 100 |
| 1945297-89 | 02-Oct-19 | Brown | Ceiling Tile | No | Client ID: BS 29.1 - D108 - Men's Change Rm - 12x12 - ACT | |
| | | | | | Cellulose | 95 |
| | | | | | Non-Fibers | 5 |
| 1945297-90 | 02-Oct-19 | Brown | Ceiling Tile | No | Client ID: BS 29.2 - D108 - Men's Change Rm - 12x12 - ACT | |
| | | | | | Cellulose | 95 |
| | | | | | Non-Fibers | 5 |
| 1945297-91 | 02-Oct-19 | Brown | Ceiling Tile | No | Client ID: BS 29.3 - D108 - Men's Change Rm - 12x12 - ACT | |
| | | | | | Cellulose | 95 |
| | | | | | Non-Fibers | 5 |

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

Asbestos, PLM Visual Estimation **MDL - 0.5%**

| Parcel ID | Sample Date | Colour | Description | Asbestos Detected | Material Identification | % Content |
|--------------|-------------|--------|--------------|-------------------|--|-----------|
| 1945297-92.1 | 02-Oct-19 | Brown | Mastic | No | Client ID: BS 30.1 - D108 - Ceiling Mastic (Pucks) | |
| | | | | | MMVF | 3 |
| | | | | | Non-Fibers | 97 |
| 1945297-92.2 | 02-Oct-19 | Grey | Ceiling Tile | No | Client ID: BS 30.1 - D108 - Ceiling Mastic (Pucks) | |
| | | | | | Cellulose | 40 |
| | | | | | MMVF | 30 |
| 1945297-93.1 | 02-Oct-19 | Brown | Mastic | No | Client ID: BS 30.2 - D108 - Ceiling Mastic (Pucks) | |
| | | | | | Non-Fibers | 100 |
| | | | | | | |
| 1945297-93.2 | 02-Oct-19 | Grey | Ceiling Tile | No | Client ID: BS 30.2 - D108 - Ceiling Mastic (Pucks) | |
| | | | | | Cellulose | 40 |
| | | | | | MMVF | 30 |
| 1945297-94.1 | 02-Oct-19 | Brown | Mastic | No | Client ID: BS 30.3 - D108 - Ceiling Mastic (Pucks) | |
| | | | | | Non-Fibers | 100 |
| | | | | | | |
| 1945297-94.2 | 02-Oct-19 | Grey | Ceiling Tile | No | Client ID: BS 30.3 - D108 - Ceiling Mastic (Pucks) | |
| | | | | | Cellulose | 40 |
| | | | | | MMVF | 30 |
| 1945297-95 | 02-Oct-19 | Grey | Plaster | No | Client ID: BS 31.1 - D108 - Ceiling Plaster | |
| | | | | | Non-Fibers | 100 |
| | | | | | | |
| 1945297-96 | 02-Oct-19 | Grey | Plaster | No | Client ID: BS 31.2 - D108 - Ceiling Plaster | |
| | | | | | Non-Fibers | 100 |
| | | | | | | |
| 1945297-97 | 02-Oct-19 | Grey | Plaster | No | Client ID: BS 31.3 - D108 - Ceiling Plaster | |
| | | | | | Non-Fibers | 100 |
| | | | | | | |

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

Asbestos, PLM Visual Estimation **MDL - 0.5%**

| Parcel ID | Sample Date | Colour | Description | Asbestos Detected | Material Identification | % Content |
|------------|-------------|--------|------------------------|-------------------|---|-----------|
| 1945297-98 | 02-Oct-19 | Grey | Insulation | No | Client ID: BS 32.1 - B100 Hallway - Sprayed Insulation | |
| | | | | | MMVF | 90 |
| | | | | | Non-Fibers | 10 |
| 1945297-99 | 02-Oct-19 | Grey | Insulation | No | Client ID: BS 32.2 - C141C - Tele Rm - Sprayed Insulation | |
| | | | | | MMVF | 90 |
| | | | | | Non-Fibers | 10 |
| 1945297-AA | 02-Oct-19 | Grey | Insulation | No | Client ID: BS 32.3 - C141C - Tele Rm - Sprayed Insulation | |
| | | | | | MMVF | 90 |
| | | | | | Non-Fibers | 10 |
| 1945297-AB | 02-Oct-19 | Grey | Insulation | No | Client ID: BS 32.4 - C201 - Sprayed Insulation | |
| | | | | | MMVF | 90 |
| | | | | | Non-Fibers | 10 |
| 1945297-AC | 02-Oct-19 | Grey | Insulation | No | Client ID: BS 32.5 - C204 - Sprayed Insulation | |
| | | | | | MMVF | 90 |
| | | | | | Non-Fibers | 10 |
| 1945297-AD | 30-Sep-19 | White | Drywall Joint Compound | No | Client ID: BS 33.1 - A136 - Drywall Joint Compound DJC | |
| | | | | | Non-Fibers | 100 |
| 1945297-AE | 01-Oct-19 | Grey | Drywall Joint Compound | No | Client ID: BS 33.2 - A139A - Drywall Joint Compound DJC | [Z-01e] |
| | | | | | Cellulose | 5 |
| | | | | | Non-Fibers | 95 |
| 1945297-AF | 02-Oct-19 | White | Drywall Joint Compound | No | Client ID: BS 33.3 - C115 - Drywall Joint Compound DJC | |
| | | | | | Non-Fibers | 100 |
| 1945297-AG | 02-Oct-19 | White | Drywall Joint Compound | No | Client ID: BS 33.4 - B215 - Drywall Joint Compound DJC | |
| | | | | | Non-Fibers | 100 |
| 1945297-AH | 02-Oct-19 | White | Drywall Joint Compound | No | Client ID: BS 33.5 - C200 Hallway - Drywall Joint Compound DJC | |
| | | | | | Non-Fibers | 100 |

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

Asbestos, PLM Visual Estimation **MDL - 0.5%**

| Parcel ID | Sample Date | Colour | Description | Asbestos Detected | Material Identification | % Content |
|--------------|-------------|-----------|------------------------|-------------------|---|-----------|
| 1945297-AI | 02-Oct-19 | White | Drywall Joint Compound | No | Client ID: BS 33.6 - E126 - Drywall Joint Compound DJC | |
| | | | | | Non-Fibers | 100 |
| 1945297-AJ | 02-Oct-19 | White | Drywall Joint Compound | No | Client ID: BS 33.7 - E053 - Drywall Joint Compound DJC | |
| | | | | | Non-Fibers | 100 |
| 1945297-AK | 03-Oct-19 | White | Drywall Joint Compound | No | Client ID: BS 34.1 - E038 - Mech. Rm - DJC | |
| | | | | | Non-Fibers | 100 |
| 1945297-AL | 03-Oct-19 | White | Drywall Joint Compound | No | Client ID: BS 34.2 - E038 - Mech. Rm - DJC | |
| | | | | | Non-Fibers | 100 |
| 1945297-AM | 03-Oct-19 | White | Drywall Joint Compound | No | Client ID: BS 34.3 - E038 - Mech. Rm - DJC | |
| | | | | | Non-Fibers | 100 |
| 1945297-AN.1 | 03-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 35.1- C115 - VFT 12x12 - Off White w/Dots | |
| | | | | | Non-Fibers | 100 |
| 1945297-AN.2 | 03-Oct-19 | | | | Client ID: BS 35.1- C115 - VFT 12x12 - Off White w/Dots | [Z-01d] |
| | | | | | not analyzed | |
| 1945297-AO.1 | 03-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 35.2- C115 - VFT 12x12 - Off White w/Dots | |
| | | | | | Non-Fibers | 100 |
| 1945297-AO.2 | 03-Oct-19 | | | | Client ID: BS 35.2- C115 - VFT 12x12 - Off White w/Dots | [Z-01d] |
| | | | | | not analyzed | |
| 1945297-AP.1 | 03-Oct-19 | Off-white | Vinyl Floor Tile | No | Client ID: BS 35.3- C115 - VFT 12x12 - Off White w/Dots | |
| | | | | | Non-Fibers | 100 |
| 1945297-AP.2 | 03-Oct-19 | Black | Mastic | No | Client ID: BS 35.3- C115 - VFT 12x12 - Off White w/Dots | |
| | | | | | Non-Fibers | 100 |

* MMVF: Man Made Vitreous Fibers: Fiberglass, Mineral Wool, Rockwool, Glasswool

** Analytes in bold indicate asbestos mineral content.

Certificate of Analysis

Report Date: 26-Nov-2019

Client: McIntosh Perry Limited (Concord)

Order Date: 4-Nov-2019

Client PO:

Project Description: Z1920014HZ-200 LEES

Analysis Summary Table

| Analysis | Method Reference/Description | Lab Location | NVLAP Lab Code * | Analysis Date |
|---------------------------------|------------------------------|-----------------|------------------|---------------|
| Asbestos, PLM Visual Estimation | by EPA 600/R-93/116 | 1 - Mississauga | 200863-0 | 7-Nov-19 |

* Reference to the NVLAP term does not permit the user of this report to claim product certification , approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government.

Mississauga Lab: 15 - 6800 Kitimat Rd Mississauga, Ontario, L5N 5M1

Qualifier Notes

Sample Qualifiers :

- Z-01: Inseparable layers.
- Z-01a: Insufficient sample.
- Z-01b: no mastic present
- Z-01c: No mastic presents.
- Z-01d: No sample present.
- Z-01e: Sample appears to be drywall.
- Z-01f: Sample contains vermiculite.

Work Order Revisions | Comments

Revision 1: Report has been revised to reflect updated sample IDs per client.



| | | |
|---|--|---|
| Client Name: MCINTOSH PERRY LTD | Project Reference: Z1920014HZ-200 Lees | Turnaround Time: <input type="checkbox"/> Immediate <input type="checkbox"/> 1 Day <input type="checkbox"/> 4 Hour <input type="checkbox"/> 2 Day <input type="checkbox"/> 8 Hour <input type="checkbox"/> 3 Day <input checked="" type="checkbox"/> Regular |
| Contact Name: ATIF MOHAMED | Quote #: | |
| Address: 6240 HIGHWAY 7, SUITE 200, WOODBRIDGE, ON, L4H 4G3 | PO #: | |
| Telephone: 647-226-6738 | Email Address: a.mohamed@mcintoshperry.com | |
| | | Date Required: |

ASBESTOS & MOLD ANALYSIS

Matrix: ☐ Air ☒ Bulk ☐ Tape Lift ☐ Swab ☐ Other Regulatory Guideline: ☒ ON ☐ QC ☐ AB ☐ SK ☐ Other:

Analyses: ☐ Microscopic Mold ☐ Culturable Mold ☐ Bacteria GRAM ☐ PCM Asbestos ☒ PLM Asbestos ☐ Chatfield Asbestos ☐ TEM Asbestos

| Paracel Order Number: 1945297 | | Sampling Date | Air Volume (L) | Analysis Required | Asbestos - Bulk | Positive Stop? |
|-------------------------------|--|---------------|----------------|-------------------|--|-------------------------------------|
| Sample ID | | | | | Identify Distinct Building Materials to Be Analyzed (if not specified, all materials identified will be analyzed) * | |
| 1 | BS 1.1 - A02-MECH.RM-UNILUX MACHINE GASKET | SEPT.30/19 | | | | <input checked="" type="checkbox"/> |
| 2 | BS 1.2- " " | SEPT.30/19 | | | | <input type="checkbox"/> |
| 3 | BS 1.3 -" " | SEPT.30/19 | | | | <input type="checkbox"/> |
| 4 | BS 2.1-104C-PARGING CEMENT | SEPT.30/19 | | | | <input type="checkbox"/> |
| 5 | BS 2.2-" " | SEPT.30/19 | | | | <input type="checkbox"/> |
| 6 | BS 2.3 - " " | SEPT.30/19 | | | | <input type="checkbox"/> |
| 7 | BS 3.1-A105-WORKBENCH#2-MECH.PIPE INSULATION | SEPT.30/19 | | | | <input type="checkbox"/> |
| 8 | BS 3.2 -" " | SEPT.30/19 | | | | <input type="checkbox"/> |
| 9 | BS 3.3-" " | SEPT.30/19 | | | | <input type="checkbox"/> |
| 10 | BS 4.1-A140-FLOOR LEVELLING COMPOUND | SEPT.30/19 | | | | <input type="checkbox"/> |
| 11 | BS 4.2-" " | SEPT.30/19 | | | | <input type="checkbox"/> |
| 12 | BS 4.3-" " | SEPT.30/19 | | | | <input checked="" type="checkbox"/> |

* If left blank, all distinct materials identified in the samples will be analyzed and reported separately as per EPA 600/R-93/116. Additional charges will apply.

| | | | | | |
|---------------------------------------|----------------------------|--------------------------|---------------------------|-----------------------------|--|
| Comments: | | | | Method of Delivery: WALK-IN | |
| Relinquished By (Sign): | Received at Depot: | Received at Lab: | Verified By: | | |
| Relinquished By (Print): ATIF MOHAMED | Date/Time: 04-NOV-19 16:26 | Date/Time: 10/5/19 11:20 | Date/Time: 20/06/19 08:19 | | |



| | |
|---|--|
| Client Name: MCINTOSH PERRY LTD | Project Reference: Z19200141Z-200 Lees |
| Contact Name: ATIF MOHAMED | Quote #: |
| Address: 6240 HIGHWAY 7, SUITE 200, WOODBRIDGE, ON, L4H 4G3 | PO #: |
| Telephone: 647-226-6738 | Email Address: a.mohamed@mcintoshperry.com |

Turnaround Time:

☐ Immediate ☐ 1 Day
☐ 4 Hour ☐ 2 Day
☐ 8 Hour ☐ 3 Day
☐ Regular

Date Required: _____

ASBESTOS & MOLD ANALYSIS

Matrix: ☐ Air ☐ Bulk ☐ Tape Lift ☐ Swab ☐ Other **Regulatory Guideline:** ☐ ON ☐ QC ☐ AB ☐ SK ☐ Other:

Analyses: ☐ Microscopic Mold ☐ Culturable Mold ☐ Bacteria GRAM ☐ PCM Asbestos ☐ PLM Asbestos ☐ Chatfield Asbestos ☐ TEM Asbestos

| Parcel Order Number: 1945297 | | Asbestos - Bulk | | | |
|--|---------------|-----------------|-------------------|--|-------------------------------------|
| Sample ID | Sampling Date | Air Volume (L) | Analysis Required | Identify Distinct Building Materials to Be Analyzed (if not specified, all materials identified will be analyzed) * | Positive Stop? |
| 1 BS 5.1 - A139-PLASTER ON COLUMNS | SEPT.30/19 | | | | <input checked="" type="checkbox"/> |
| 2 BS 5.2 - " " | SEPT.30/19 | | | | <input type="checkbox"/> |
| 3 BS 5.3 - " " | SEPT.30/19 | | | | <input type="checkbox"/> |
| 4 BS 6.1-A144-HIGH TRAFFIC COATING | SEPT.30/19 | | | | <input type="checkbox"/> |
| 5 BS 6.2 - " " | SEPT.30/19 | | | | <input type="checkbox"/> |
| 6 BS 6.3 - " " | SEPT.30/19 | | | | <input type="checkbox"/> |
| 7 BS 7.1-A139-INT. WINDOW CAULKING | SEPT.30/19 | | | | <input type="checkbox"/> |
| 8 BS 7.2 - " " | SEPT.30/19 | | | | <input type="checkbox"/> |
| 9 BS 7.3 - " " | SEPT.30/19 | | | | <input type="checkbox"/> |
| 10 BS 8.1-A136-VFT(12"X12"-OFFWHITE W/GRAY&BLACK STREAKS | SEPT.30/19 | | | | <input type="checkbox"/> |
| 11 BS 8.2 - " " | SEPT.30/19 | | | | <input checked="" type="checkbox"/> |
| 12 BS 8.3 - " " | SEPT.30/19 | | | | <input checked="" type="checkbox"/> |

* If left blank, all distinct materials identified in the samples will be analyzed and reported separately as per EPA 600/R-93/116. Additional charges will apply.

| | | | | |
|--------------------------|----------------------------|---------------------------|-----------------------------|--|
| Comments: | | | Method of Delivery: WALK-IN | |
| Relinquished By (Sign): | Received at Depot: | Received at Lab: | Verified By: | |
| Relinquished By (Print): | Date/Time: 04-NOV-19 16:26 | Date/Time: 11/05/19 11:00 | Date/Time: 2019/11/05 08:19 | |



| | |
|---|--|
| Client Name: MCINTOSH PERRY LTD | Project Reference: Z1920014HZ-200 Lees |
| Contact Name: ATIF MOHAMED | Quote #: |
| Address: 6240 HIGHWAY 7, SUITE 200, WOODBRIDGE, ON, L4H 4G3 | PO #: |
| Telephone: 647-226-6738 | Email Address: a.mohamed@mcintoshperry.com |

Turnaround Time:

☐ Immediate ☐ 1 Day
☐ 4 Hour ☐ 2 Day
☐ 8 Hour ☐ 3 Day
☐ Regular

Date Required: _____

ASBESTOS & MOLD ANALYSIS

Matrix: ☐ Air ☐ Bulk ☐ Tape Lift ☐ Swab ☐ Other **Regulatory Guideline:** ☐ ON ☐ QC ☐ AB ☐ SK ☐ Other:

Analyses: ☐ Microscopic Mold ☐ Culturable Mold ☐ Bacteria GRAM ☐ PCM Asbestos ☐ PLM Asbestos ☐ Chatfield Asbestos ☐ TEM Asbestos

Parcel Order Number:

1945297

| Sample ID | | Sampling Date | Air Volume (L) | Analysis Required | Asbestos - Bulk | Positive Stop? |
|-----------|---|---------------|----------------|-------------------|---|-------------------------------------|
| | | | | | Identify Distinct Building Materials to Be Analyzed (if not specified, all materials identified will be analyzed) * | |
| 1 | BS 9.1 - A138E-VFT(12"X12"-BEIGE WBROWN&GREY FLAKES) | OCT.1/19 | | | | <input checked="" type="checkbox"/> |
| 2 | BS 9.2-" " | OCT.1/19 | | | | <input checked="" type="checkbox"/> |
| 3 | BS 9.3-" " | OCT.1/19 | | | | <input type="checkbox"/> |
| 4 | BS 10.1-A122B-VFT(12"X12"-OLIVE GREEN W/GRAY FLAKES) | OCT.1/19 | | | | <input type="checkbox"/> |
| 5 | BS 10.2-" " | OCT.1/19 | | | | <input type="checkbox"/> |
| 6 | BS 10.3-" " | OCT.1/19 | | | | <input type="checkbox"/> |
| 7 | BS 11.1-A147-ARCHIVES RM-VFT(12"X12"-GREY W/BLUE STREAKS) | OCT.1/19 | | | | <input type="checkbox"/> |
| 8 | BS 11.2-" " | OCT.1/19 | | | | <input type="checkbox"/> |
| 9 | BS 11.3-" " | OCT.1/19 | | | | <input type="checkbox"/> |
| 10 | BS 12.1-A122B-VFT(12"X12"-OFFWHITE W/BROWN FLAKES) | OCT.1/19 | | | | <input type="checkbox"/> |
| 11 | BS 12.2-" " | OCT.1/19 | | | | <input type="checkbox"/> |
| 12 | BS 12.3-" " | OCT.1/19 | | | | <input checked="" type="checkbox"/> |

* If left blank, all distinct materials identified in the samples will be analyzed and reported separately as per EPA 600/R-93/116. Additional charges will apply.

Comments:

Method of Delivery:

WALK-IN

| | | | |
|--------------------------|----------------------------|--------------------------|----------------------------|
| Relinquished By (Sign): | Received at Depot: | Received at Lab: | Verified By: |
| | | | |
| Relinquished By (Print): | Date/Time: 04-NOV-19 16:26 | Date/Time: 7/10/19 11:20 | Date/Time: Nov 06/19 08:19 |



| | |
|---|--|
| Client Name: MCINTOSH PERRY LTD | Project Reference: Z1920014HZ-200 Lees |
| Contact Name: ATIF MOHAMED | Quote #: |
| Address: 6240 HIGHWAY 7, SUITE 200, WOODBRIDGE, ON, L4H 4G3 | PO #: |
| Telephone: 647-226-6738 | Email Address: a.mohamed@mcintoshperry.com |

Turnaround Time:

- ☐ Immediate ☐ 1 Day
☐ 4 Hour ☐ 2 Day
☐ 8 Hour ☐ 3 Day
☐ Regular

Date Required:

ASBESTOS & MOLD ANALYSIS

Matrix: ☐ Air ☐ Bulk ☐ Tape Lift ☐ Swab ☐ Other Regulatory Guideline: ☐ ON ☐ QC ☐ AB ☐ SK ☐ Other:

Analyses: ☐ Microscopic Mold ☐ Culturable Mold ☐ Bacteria GRAM ☐ PCM Asbestos ☐ PLM Asbestos ☐ Chatfield Asbestos ☐ TEM Asbestos

Paracel Order Number:

1945297

| Sample ID | | Sampling Date | Air Volume (L) | Analysis Required | Asbestos - Bulk | Positive Stop? |
|-----------|------------------------------------|---------------|----------------|-------------------|---|-------------------------------------|
| | | | | | Identify Distinct Building Materials to Be Analyzed (if not specified, all materials identified will be analyzed) * | |
| 1 | BS 13.1-A142-CONCRETE BLOCK MORTAR | OCT.1/19 | | | | <input checked="" type="checkbox"/> |
| 2 | BS 13.2- " " | OCT.1/19 | | | | <input checked="" type="checkbox"/> |
| 3 | BS 13.3- " " | OCT.1/19 | | | | <input checked="" type="checkbox"/> |
| 4 | BS 14.1-A106C-WALL TILE GROUT | OCT.1/19 | | | | <input checked="" type="checkbox"/> |
| 5 | BS 14.2- " " | OCT.1/19 | | | | <input checked="" type="checkbox"/> |
| 6 | BS 14.3- " " | OCT.1/19 | | | | <input checked="" type="checkbox"/> |
| 7 | BS 15.1-A139-WALL TEXTURE COATING | OCT.1/19 | | | | <input checked="" type="checkbox"/> |
| 8 | BS 15.2- " " | OCT.1/19 | | | | <input checked="" type="checkbox"/> |
| 9 | BS 15.3- " " | OCT.1/19 | | | | <input checked="" type="checkbox"/> |
| 10 | BS 15.4- " " | OCT.1/19 | | | | <input checked="" type="checkbox"/> |
| 11 | BS 15.5-A140- " " | OCT.1/19 | | | | <input checked="" type="checkbox"/> |
| 12 | BS 15.6- " " | OCT.1/19 | | | | <input checked="" type="checkbox"/> |

* If left blank, all distinct materials identified in the samples will be analyzed and reported separately as per EPA 600/R-93/116. Additional charges will apply.

Comments:

Method of Delivery:

WALK-IN

| | | | |
|--------------------------|----------------------------|---------------------------|----------------------------|
| Relinquished By (Sign): | Received at Depot: | Received at Lab: | Verified By: |
| | | | |
| Relinquished By (Print): | Date/Time: 04-NOV-19 16:26 | Date/Time: 7/NOV/19 11:20 | Date/Time: 20/NOV/19 08:19 |

Parcel ID: 1945297



Office
319 St. Laurent Blvd.
3, Ontario K1G 4J8
30-749-1947
icel@paracellabs.com

Chain of Custody
(Lab Use Only)

Page 5 of 10

Turnaround Time:

- ☐ Immediate ☐ 1 Day
☐ 4 Hour ☐ 2 Day
☐ 8 Hour ☐ 3 Day
☐ Regular

Date Required:

ASBESTOS & MOLD ANALYSIS

Matrix: ☐ Air ☐ Bulk ☐ Tape Lift ☐ Swab ☐ Other Regulatory Guideline: ☐ ON ☐ QC ☐ AB ☐ SK ☐ Other:

Analyses: ☐ Microscopic Mold ☐ Culturable Mold ☐ Bacteria GRAM ☐ PCM Asbestos ☐ PLM Asbestos ☐ Chatfield Asbestos ☐ TEM Asbestos

Parcel Order Number:

1945297

| Sample ID | | Sampling Date | Air Volume (L) | Analysis Required | Asbestos - Bulk Identify Distinct Building Materials to Be Analyzed (if not specified, all materials identified will be analyzed) * | Positive Stop? |
|-----------|---|---------------|----------------|-------------------|---|-------------------------------------|
| 1 | BS 15.7-" | OCT.1/19 | | | | <input checked="" type="checkbox"/> |
| 2 | BS 16.1-A36-2X4-SCT-FISSURES | OCT.1/19 | | | | <input type="checkbox"/> |
| 3 | BS 16.2 - " | OCT.1/19 | | | | <input type="checkbox"/> |
| 4 | BS 16.3- " | OCT.1/19 | | | | <input type="checkbox"/> |
| 5 | BS 17.1-A106-2X4-SCT-PINHOLES WITH LARGE FISSURES | OCT.1/19 | | | | <input type="checkbox"/> |
| 6 | BS 17.2-A100B-" | OCT.1/19 | | | | <input type="checkbox"/> |
| 7 | BS 17.3-A127C-" | OCT.1/19 | | | | <input type="checkbox"/> |
| 8 | BS 18.1-A106C-VFT(12"x12"-RED W/FLAKES) | OCT.1/19 | | | | <input type="checkbox"/> |
| 9 | BS 18.2-" | OCT.1/19 | | | | <input type="checkbox"/> |
| 10 | BS 18.3-" | OCT.1/19 | | | | <input type="checkbox"/> |
| 11 | BS 19.1-B202B-CARPET MASTIC | OCT.1/19 | | | | <input type="checkbox"/> |
| 12 | BS 19.2-" | OCT.1/19 | | | | <input type="checkbox"/> |

* If left blank, all distinct materials identified in the samples will be analyzed and reported separately as per EPA 600/R-93/116. Additional charges will apply.

Comments:

Method of Delivery:

WALK-IN

Relinquished By (Sign):

Received at Depot:

Received at Lab:

Verified By:

Relinquished By (Print):

Date/Time:

04-Nov-19 16:26

Date/Time:

7/11/19 11:26

Date/Time:

Nov 06/19 08:19



| | |
|---|--|
| Client Name: MCINTOSH PERRY LTD | Project Reference: Z1920014HZ-200 Lees |
| Contact Name: ATIF MOHAMED | Quote #: |
| Address: 6240 HIGHWAY 7, SUITE 200, WOODBRIDGE, ON, L4H 4G3 | PO #: |
| Telephone: 647-226-6738 | Email Address: a.mohamed@mcintoshperry.com |

Turnaround Time:

- ☐ Immediate ☐ 1 Day
☐ 4 Hour ☐ 2 Day
☐ 8 Hour ☐ 3 Day
☐ Regular

Date Required: _____

ASBESTOS & MOLD ANALYSIS

Matrix: ☐ Air ☐ Bulk ☐ Tape Lift ☐ Swab ☐ Other **Regulatory Guideline:** ☐ ON ☐ QC ☐ AB ☐ SK ☐ Other:

Analyses: ☐ Microscopic Mold ☐ Culturable Mold ☐ Bacteria GRAM ☐ PCM Asbestos ☐ PLM Asbestos ☐ Chatfield Asbestos ☐ TEM Asbestos

Parcel Order Number:

1945297

| Sample ID | | Sampling Date | Air Volume (L) | Analysis Required | Asbestos - Bulk | Positive Stop? |
|-----------|--|---------------|----------------|-------------------|---|-------------------------------------|
| | | | | | Identify Distinct Building Materials to Be Analyzed (if not specified, all materials identified will be analyzed) * | |
| 1 | BS 19.3-" | OCT.1/19 | | | | <input checked="" type="checkbox"/> |
| 2 | BS 20.1-BS21SE-VFT(2"X2"-OFFWHITE W/BUE STREAKS) | OCT.1/19 | | | | <input type="checkbox"/> |
| 3 | BS 20.2-" | OCT.1/19 | | | | <input type="checkbox"/> |
| 4 | BS 20.3-" | OCT.1/19 | | | | <input type="checkbox"/> |
| 5 | BS 21.1-B215N-PLASTER ON BEAM | OCT.1/19 | | | | <input type="checkbox"/> |
| 6 | BS 21.2-" | OCT.1/19 | | | | <input type="checkbox"/> |
| 7 | BS 21.3-" | OCT.1/19 | | | | <input type="checkbox"/> |
| 8 | BS 22.1-C209-VFT(12"X12"-OFFWHITE W/GREY&BLACK FLAKES) | OCT.1/19 | | | | <input type="checkbox"/> |
| 9 | BS 22.2-" | OCT.1/19 | | | | <input type="checkbox"/> |
| 10 | BS 22.3-" | OCT.1/19 | | | | <input type="checkbox"/> |
| 11 | BS 23.1-C209-VFT(12"X12"-BEIGE W/MULTICOLOUR FLAKES) | OCT.1/19 | | | | <input type="checkbox"/> |
| 12 | BS 23.2-" | OCT.1/19 | | | | <input checked="" type="checkbox"/> |

* If left blank, all distinct materials identified in the samples will be analyzed and reported separately as per EPA 600/R-93/116. Additional charges will apply.

Comments:

Method of Delivery:

WALK-IN

| | | | |
|--------------------------|----------------------------|---------------------------|----------------------------|
| Relinquished By (Sign): | Received at Depot: | Received at Lab: | Verified By: |
| Relinquished By (Print): | Date/Time: 04-Nov-19 16:26 | Date/Time: Nov 5/19 11:40 | Date/Time: Nov 06/19 08:19 |

Paracel ID: 1945297



Office
19 St. Laurent Blvd.
Ontario K1G 4J8
0-749-1947
cel@paracellabs.com

Chain of Custody
(Lab Use Only)

Page 7 of 10

Turnaround Time:

- ☐ Immediate ☐ 1 Day
☐ 4 Hour ☐ 2 Day
☐ 8 Hour ☐ 3 Day
☐ Regular

Date Required: _____

| | |
|---|--|
| Client Name: MCINTOSH PERRY LTD | Project Reference: Z1920014HZ-200 Lees |
| Contact Name: ATIF MOHAMED | Quote #: |
| Address: 6240 HIGHWAY 7, SUITE 200, WOODBRIDGE, ON, L4H 4G3 | PO #: |
| Telephone: 647-226-6738 | Email Address: a.mohamed@mcintoshperry.com |

ASBESTOS & MOLD ANALYSIS

Matrix: ☐ Air ☐ Bulk ☐ Tape Lift ☐ Swab ☐ Other **Regulatory Guideline:** ☐ ON ☐ QC ☐ AB ☐ SK ☐ Other:

Analyses: ☐ Microscopic Mold ☐ Culturable Mold ☐ Bacteria GRAM ☐ PCM Asbestos ☐ PLM Asbestos ☐ Chatfield Asbestos ☐ TEM Asbestos

Paracel Order Number:

1945297

| Sample ID | | Sampling Date | Air Volume (L) | Analysis Required | Asbestos - Bulk | Positive Stop? |
|-----------|---|---------------|----------------|-------------------|---|-------------------------------------|
| | | | | | Identify Distinct Building Materials to Be Analyzed (if not specified, all materials identified will be analyzed) * | |
| 1 | BS 23.3-" | OCT.2/19 | | | | <input type="checkbox"/> |
| 2 | BS 24.1-C200HALLWAY-VFT(12"X12"-OFFWHITE W/GRAY FLAKES) | OCT.2/19 | | | | <input checked="" type="checkbox"/> |
| 3 | BS 24.2-" | OCT.2/19 | | | | <input type="checkbox"/> |
| 4 | BS 24.3- C144-" | OCT.2/19 | | | | <input type="checkbox"/> |
| 5 | BS 25.1-C115-VFT(12"X12"-PINK W/DOTS) | OCT.2/19 | | | | <input type="checkbox"/> |
| 6 | BS 25.2" | OCT.2/19 | | | | <input type="checkbox"/> |
| 7 | BS 25.3-" | OCT.2/19 | | | | <input type="checkbox"/> |
| 8 | BS 26.1-E041-VFT(12"X12"-OFFWHITE W/BLUE STREAKS) | OCT.2/19 | | | | <input type="checkbox"/> |
| 9 | BS 26.2-" | OCT.2/19 | | | | <input type="checkbox"/> |
| 10 | BS 26.3-" | OCT.2/19 | | | | <input type="checkbox"/> |
| 11 | BS 27.1-E053-VFT(12"X12"-GREY W/WHITE & LIGHT GREY STREAKS) | OCT.2/19 | | | | <input type="checkbox"/> |
| 12 | BS 27.2-" | OCT.2/19 | | | | <input checked="" type="checkbox"/> |

* If left blank, all distinct materials identified in the samples will be analyzed and reported separately as per EPA 600/R-93/116. Additional charges will apply.

Comments:

Method of Delivery:

WALK-IN

Relinquished By (Sign):

Received at Depot:

Received at Lab:

Verified By:

Relinquished By (Print):

Date/Time:

Date/Time:

Date/Time:

Paracel ID: 1945297



100
1 St. Laurent Blvd.
Toronto K1G 4J8
416-749-1947
info@paracellabs.com

Chain of Custody
(Lab Use Only)

Page 8 of 10

Turnaround Time:

- ☐ Immediate ☐ 1 Day
☐ 4 Hour ☐ 2 Day
☐ 8 Hour ☐ 3 Day
☐ Regular

Date Required: _____

| | |
|---|--|
| Client Name: MCINTOSH PERRY LTD | Project Reference: Z1920014HZ-200 Lees |
| Contact Name: ATIF MOHAMED | Quote #: |
| Address: 6240 HIGHWAY 7, SUITE 200, WOODBRIDGE, ON, L4H 4G3 | PO #: |
| Telephone: 647-226-6738 | Email Address: a.mohamed@mcintoshperry.com |

ASBESTOS & MOLD ANALYSIS

Matrix: ☐ Air ☐ Bulk ☐ Tape Lift ☐ Swab ☐ Other Regulatory Guideline: ☐ ON ☐ QC ☐ AB ☐ SK ☐ Other:

Analyses: ☐ Microscopic Mold ☐ Culturable Mold ☐ Bacteria GRAM ☐ PCM Asbestos ☐ PLM Asbestos ☐ Chatfield Asbestos ☐ TEM Asbestos

Paracel Order Number:

1945297

| Sample ID | | Sampling Date | Air Volume (L) | Analysis Required | Asbestos - Bulk | Positive Stop? |
|-----------|--|---------------|----------------|-------------------|---|-------------------------------------|
| | | | | | Identify Distinct Building Materials to Be Analyzed (if not specified, all materials identified will be analyzed) * | |
| 1 | BS 27.3-" | OCT.2/19 | | | | <input checked="" type="checkbox"/> |
| 2 | BS 28.1-E244-VFT(12"X12"-OFFWHITE W/GREY FLAKES) | OCT.2/19 | | | | <input checked="" type="checkbox"/> |
| 3 | BS 28.2-" | OCT.2/19 | | | | <input type="checkbox"/> |
| 4 | BS 28.3-" | OCT.2/19 | | | | <input type="checkbox"/> |
| 5 | BS 29.1-D108-MEN'S CHANGE RM-12"X12"-ACT | OCT.2/19 | | | | <input type="checkbox"/> |
| 6 | BS 29.2-" | OCT.2/19 | | | | <input type="checkbox"/> |
| 7 | BS 29.3-" | OCT.2/19 | | | | <input type="checkbox"/> |
| 8 | BS 301.-D108-CEILING MASTIC (PUCKS) | OCT.2/19 | | | | <input type="checkbox"/> |
| 9 | BS 30.2-" | OCT.2/19 | | | | <input type="checkbox"/> |
| 10 | BS 30.3-" | OCT.2/19 | | | | <input type="checkbox"/> |
| 11 | BS 31.1-D108-CEILING PLASTER | OCT.2/19 | | | | <input type="checkbox"/> |
| 12 | BS 31.2-" | OCT.2/19 | | | | <input type="checkbox"/> |

* If left blank, all distinct materials identified in the samples will be analyzed and reported separately as per EPA 600/R-93/116. Additional charges will apply.

Comments:

Method of Delivery:

WALK-IN

Relinquished By (Sign):

Received at Depot:

Received at Lab:

Verified By:

Relinquished By (Print):

Date/Time:

Date/Time:

Date/Time:

Chain of Custody (Asbestos) - Rev. 3.0 Dec. 2018

04-NOV-19 16:26

NOV 5/19 11:20

NOV 06/19 08:19

Paracel ID: 1945297



ice
St. Laurent Blvd.
Ontario K1G 4J8
749-1947
laparacellabs.com

Chain of Custody
(Lab Use Only)

Page 9 of 10

| | |
|---|--|
| Client Name: MCINTOSH PERRY LTD | Project Reference: Z1920014HZ-200 Lees |
| Contact Name: ATIF MOHAMED | Quote #: |
| Address: 6240 HIGHWAY 7, SUITE 200, WOODBRIDGE, ON, L4H 4G3 | PO #: |
| Telephone: 647-226-6738 | Email Address: a.mohamed@mcintoshperry.com |

Turnaround Time:

☐ Immediate ☐ 1 Day
☐ 4 Hour ☐ 2 Day
☐ 8 Hour ☐ 3 Day
☐ Regular

Date Required:

ASBESTOS & MOLD ANALYSIS

Matrix: ☐ Air ☐ Bulk ☐ Tape Lift ☐ Swab ☐ Other **Regulatory Guideline:** ☐ ON ☐ QC ☐ AB ☐ SK ☐ Other:

Analyses: ☐ Microscopic Mold ☐ Culturable Mold ☐ Bacteria GRAM ☐ PCM Asbestos ☐ PLM Asbestos ☐ Chatfield Asbestos ☐ TEM Asbestos

Paracel Order Number:

1945297

| Sample ID | | Sampling Date | Air Volume (L) | Analysis Required | Asbestos - Bulk Identify Distinct Building Materials to Be Analyzed (if not specified, all materials identified will be analyzed) * | Positive Stop? |
|-----------|---|---------------|----------------|-------------------|---|-------------------------------------|
| 1 | BS 31.3-" | OCT.2/19 | | | | <input checked="" type="checkbox"/> |
| 2 | BS 32.1-B100HALLWAY-SPRAYED INSULATION | OCT.2/19 | | | | <input checked="" type="checkbox"/> |
| 3 | BS 32.2-C141C-TELERM-" | OCT.2/19 | | | | <input type="checkbox"/> |
| 4 | BS 32.3-" | OCT.2/19 | | | | <input type="checkbox"/> |
| 5 | BS 32.4-C201-SPRAYED INSULATION | OCT.2/19 | | | | <input type="checkbox"/> |
| 6 | BS 32.5-C204" | OCT.2/19 | | | | <input type="checkbox"/> |
| 7 | BS 33.1-A136-DRYWALL JOINT COMPOUND (DJC) | SEPT.30/19 | | | | <input type="checkbox"/> |
| 8 | BS 33.2-A139A-DJC | OCT.1/19 | | | | <input type="checkbox"/> |
| 9 | BS 33.3-C115-DJC | OCT.2/19 | | | | <input type="checkbox"/> |
| 10 | BS 33.4-B215-DJC | OCT.2/19 | | | | <input type="checkbox"/> |
| 11 | BS 33.5-C200HALLWAY-DJC | OCT.2/19 | | | | <input type="checkbox"/> |
| 12 | BS 33.6-E126-DJC | OCT.2/19 | | | | <input checked="" type="checkbox"/> |

* If left blank, all distinct materials identified in the samples will be analyzed and reported separately as per EPA 600/R-93/116. Additional charges will apply.

Comments:

Method of Delivery:

WALK-IN

Relinquished By (Sign):

Received at Depot:

Received at Lab:

Verified By:

Relinquished By (Print):

Date/Time:

Date/Time:

Date/Time:



| | | |
|---|--|--|
| Client Name: MCINTOSH PERRY LTD | Project Reference: Z1920014HZ-200 Lees | Turnaround Time: <input type="checkbox"/> Immediate <input type="checkbox"/> 1 Day <input type="checkbox"/> 4 Hour <input type="checkbox"/> 2 Day <input type="checkbox"/> 8 Hour <input type="checkbox"/> 3 Day <input type="checkbox"/> Regular Date Required: _____ |
| Contact Name: ATIF MOHAMED | Quote #: | |
| Address: 6240 HIGHWAY 7, SUITE 200, WOODBRIDGE, ON, L4H 4G3 | PO #: | |
| Telephone: 647-226-6738 | Email Address: a.mohamed@mcintoshperry.com | |

ASBESTOS & MOLD ANALYSIS

Matrix: ☐ Air ☐ Bulk ☐ Tape Lift ☐ Swab ☐ Other
 Regulatory Guideline: ☐ ON ☐ QC ☐ AB ☐ SK ☐ Other:

Analyses: ☐ Microscopic Mold ☐ Culturable Mold ☐ Bacteria GRAM ☐ PCM Asbestos ☐ PLM Asbestos ☐ Chatfield Asbestos ☐ TEM Asbestos

| Paracel Order Number: 1945297 | | Sampling Date | Air Volume (L) | Analysis Required | Asbestos - Bulk | |
|-------------------------------|---|---------------|----------------|-------------------|---|-------------------------------------|
| Sample ID | | | | | Identify Distinct Building Materials to Be Analyzed (if not specified, all materials identified will be analyzed) * | Positive Stop? |
| 1 | BS 33.7-E053-DJC | OCT.2/19 | | | | <input checked="" type="checkbox"/> |
| 2 | BS 34.1-E038-MECH.RM-DJC | OCT.3/19 | | | | <input type="checkbox"/> |
| 3 | BS 34.2-" " | OCT.3/19 | | | | <input type="checkbox"/> |
| 4 | BS 34.3-" " | OCT.3/19 | | | | <input type="checkbox"/> |
| 5 | BS 35.1-C115-VFT(12"X12"-OFFWHITE W/DOTS) | OCT.3/19 | | | | <input type="checkbox"/> |
| 6 | BS 35.2-" " | OCT.3/19 | | | | <input type="checkbox"/> |
| 7 | BS 35.3-" " | OCT.3/19 | | | | <input type="checkbox"/> |
| 8 | | | | | | <input type="checkbox"/> |
| 9 | | | | | | <input type="checkbox"/> |
| 10 | | | | | | <input type="checkbox"/> |
| 11 | | | | | | <input type="checkbox"/> |
| 12 | | | | | | <input checked="" type="checkbox"/> |

* If left blank, all distinct materials identified in the samples will be analyzed and reported separately as per EPA 600/R-93/116. Additional charges will apply.

| | | | | | |
|--------------------------|----------------------------|--------------------------|----------------------------|-----------------------------|--|
| Comments: | | | | Method of Delivery: WALK-IN | |
| Relinquished By (Sign): | Received at Depot: | Received at Lab: | Verified By: | | |
| | | | | | |
| Relinquished By (Print): | Date/Time: 04-Nov-19 16:26 | Date/Time: 7/10/19 11:20 | Date/Time: Nov 06/19 08:19 | | |

Certificate of Analysis

McIntosh Perry Limited (Concord)

6240 Hwy 7, Suite 200
Woodbridge, ON L4H 0R2
Attn: Atif Mohamed

Client PO:
Project: Z1920014HZ-200 LEES
Custody:

Report Date: 8-Nov-2019
Order Date: 4-Nov-2019

Order #: 1945256

This Certificate of Analysis contains analytical data applicable to the following samples as submitted:

| Paracel ID | Client ID |
|------------|----------------------------------|
| 1945256-01 | PB-1-A140-BEIGE, ABOVE DOOR VENT |
| 1945256-02 | PB-2-A140-BLUE, DOOR |
| 1945256-03 | PB-3-A144-BEIGE, FLOOR |
| 1945256-04 | PB-4-D109-MAROON, WALL |
| 1945256-05 | PB-5-A122-BLACK, WALL |
| 1945256-06 | PB-6-D201-WHITE, ON DUCTS |
| 1945256-07 | PB-7-208B-TEAL GREEN, WALL |
| 1945256-08 | PB-8-E254-OFF WHITE, WALL |
| 1945256-09 | PB-9-A02-MECH. RM-GREY, FLOOR |

Approved By:



Mark Foto, M.Sc.
Lab Supervisor

Any use of these results implies your agreement that our total liability in connection with this work, however arising shall be limited to the amount paid by you for this work, and that our employees or agents shall not under circumstances be liable to you in connection with this work

Certificate of Analysis

Client: McIntosh Perry Limited (Concord)

Client PO:

Report Date: 08-Nov-2019

Order Date: 4-Nov-2019

Project Description: Z1920014HZ-200 LEES

Analysis Summary Table

| Analysis | Method Reference/Description | Extraction Date | Analysis Date |
|----------------|-------------------------------|-----------------|---------------|
| Metals, ICP-MS | EPA 6020 - Digestion - ICP-MS | 6-Nov-19 | 7-Nov-19 |

Sample and QC Qualifiers Notes

1- GEN01 :Elevated Reporting Limits due to limited sample volume.

Sample Data Revisions

None

Work Order Revisions/Comments:

None

Other Report Notes:

n/a: not applicable

ND: Not Detected

MDL: Method Detection Limit

Source Result: Data used as source for matrix and duplicate samples

%REC: Percent recovery.

RPD: Relative percent difference.

Certificate of Analysis
 Client: McIntosh Perry Limited (Concord)
 Client PO:

Report Date: 08-Nov-2019
 Order Date: 4-Nov-2019
 Project Description: Z1920014HZ-200 LEES

Sample Results

| Lead | | | | Matrix: Paint Sample Date: 01-Oct-19 |
|------------|-------------------------------|-------|--------|---|
| Paracel ID | Client ID | Units | MDL | Result |
| 1945256-04 | PB-4-D109-MAROON, WALL | % | 0.0005 | <0.0019 [1] |
| 1945256-05 | PB-5-A122-BLACK, WALL | % | 0.0005 | 0.0579 |
| 1945256-06 | PB-6-D201-WHITE, ON DUCTS | % | 0.0005 | 0.167 |
| 1945256-07 | PB-7-208B-TEAL GREEN, WALL | % | 0.0005 | 0.0006 |
| 1945256-08 | PB-8-E254-OFF WHITE, WALL | % | 0.0005 | 0.0020 |
| 1945256-09 | PB-9-A02-MECH. RM-GREY, FLOOR | % | 0.0005 | 0.189 |

| Lead | | | | Matrix: Paint Sample Date: 30-Sep-19 |
|------------|----------------------------------|-------|--------|---|
| Paracel ID | Client ID | Units | MDL | Result |
| 1945256-01 | PB-1-A140-BEIGE, ABOVE DOOR VENT | % | 0.0005 | 0.0753 |
| 1945256-02 | PB-2-A140-BLUE, DOOR | % | 0.0005 | 0.0008 |
| 1945256-03 | PB-3-A144-BEIGE, FLOOR | % | 0.0005 | 0.0173 |

Laboratory Internal QA/QC

| Analyte | Result | Reporting Limit | Units | Source Result | %REC | %REC Limit | RPD | RPD Limit | Notes |
|-------------------------|--------|-----------------|-------|---------------|------|------------|-----|-----------|-------|
| Matrix Blank | | | | | | | | | |
| Lead | ND | 0.0005 | % | | | | | | |
| Matrix Duplicate | | | | | | | | | |
| Lead | ND | 0.0005 | % | 0.00082 | | | 0.0 | 50 | |
| Matrix Spike | | | | | | | | | |
| Lead | 0.129 | 0.0005 | % | 0.00082 | 102 | 70-130 | | | |



1945256

| | | | | | |
|--|--|-------------------------------------|--|---|--|
| Client Name: MCINTOSH PERRY LIMITED | | Project Ref: Z1920014HZ-200 LEES | | Page 1 of 1 | |
| Contact Name: ATIF MOHAMED | | Quote #: | | Turnaround Time | |
| Address: 6240 HIGHWAY 7, SUITE 200, WOODBRIDGE, ONTARIO, L4H 4 | | PO #: | | <input type="checkbox"/> 1 day <input type="checkbox"/> 3 day <input type="checkbox"/> 2 day <input checked="" type="checkbox"/> Regular | |
| Telephone: 647-226-6738 | | E-mail: a.mohamed@mcintoshperry.com | | Date Required: | |

| Regulation 153/04 | | Other Regulation | | Matrix Type: S (Soil/Sed.) GW (Ground Water) SW (Surface Water) SS (Storm/Sanitary Sewer) P (Paint) A (Air) O (Other) | | Required Analysis | | | | | | | | | | | | | | | | | |
|---|----------------------------------|--|--|---|------------|-------------------|--------------|------|------|--|--|--|--|--|--|--|--|--|--|--|--|--|--|
| <input type="checkbox"/> Table 1 <input type="checkbox"/> Res/Park <input type="checkbox"/> Med/Fine <input type="checkbox"/> Table 2 <input type="checkbox"/> Ind/Comm <input type="checkbox"/> Coarse <input type="checkbox"/> Table 3 <input type="checkbox"/> Agri/Other <input type="checkbox"/> Table _____ For RSC: <input type="checkbox"/> Yes <input type="checkbox"/> No | | <input type="checkbox"/> REG 558 <input type="checkbox"/> PWQO <input type="checkbox"/> CCME <input type="checkbox"/> MISA <input type="checkbox"/> SU - Sani <input type="checkbox"/> SU - Storm Mun: _____ <input type="checkbox"/> Other: _____ | | Matrix | Air Volume | # of Containers | Sample Taken | | LEAD | | | | | | | | | | | | | | |
| Sample ID/Location Name | | | | | | | Date | Time | | | | | | | | | | | | | | | |
| 1 | PB-1-A140-BEIGE, ABOVE DOOR VENT | | | P | | | SEPT.30/19 | | X | | | | | | | | | | | | | | |
| 2 | PB-2-A140-BLUE, DOOR | | | P | | | SEPT.30/19 | | X | | | | | | | | | | | | | | |
| 3 | PB-3-A144-BEIGE, FLOOR | | | P | | | SEPT.30/19 | | X | | | | | | | | | | | | | | |
| 4 | PB-4-D109-MAROON, WALL | | | P | | | OCT.1/19 | | X | | | | | | | | | | | | | | |
| 5 | PB-5-A122-BLACK, WALL | | | P | | | OCT.1/19 | | X | | | | | | | | | | | | | | |
| 6 | PB-6-D201-WHITE, ON DUCTS | | | P | | | OCT.1/19 | | X | | | | | | | | | | | | | | |
| 7 | PB-7-208B-TEAL GREEN, WALL | | | P | | | OCT.1/19 | | X | | | | | | | | | | | | | | |
| 8 | PB-8-E254-OFFWHITE, WALL | | | P | | | OCT.1/19 | | X | | | | | | | | | | | | | | |
| 9 | PB-9-A02-MECH.RM.-GREY, FLOOR | | | P | | | OCT.1/19 | | X | | | | | | | | | | | | | | |
| 10 | | | | | | | | | X | | | | | | | | | | | | | | |

| | | | | | | | |
|---------------------------------|--|----------------------------|--|----------------------------|--|---|--|
| Comments: | | | | Method of Delivery: | | | |
| Relinquished By (Sign): | | Received By Driver/Depot: | | Received at Lab: | | Verified By: | |
| Relinquished By (Print): ATIF M | | Date/Time: 04-NOV-19 16:26 | | Date/Time: 04-NOV-19 16:26 | | Date/Time: 04-NOV-19 16:04 | |
| Date/Time: | | Temperature: °C | | Temperature: N/A | | pH Verified: <input type="checkbox"/> By: | |

APPENDIX D

Site Photographs



Photo 1: View of asbestos-containing interior window caulking (black) observed to be in good condition in Room 139.



Photo 2: View of asbestos-containing mechanical pipe straight insulation observed to be in poor condition in cabinet 510 in Room A 105.



Photo 3: View of asbestos-containing mechanical pipe straight insulation observed to be in poor condition on the 2nd work bench outside the bike shop office in Room A 105.



Photo 4: View of asbestos-containing mechanical pipe fittings observed to be in poor condition in Room A104.

This damage has been repaired.



Photo 5: View of asbestos-containing plaster on steel mesh observed in Room B 215N.



Photo 6: View of asbestos-containing pipe gasket observed on the Unilux Boiler in Mechanical Room A02.



Photo 7: View of asbestos-containing transite pipe (highlighted in red) observed to be in good condition Mechanical Room A138C.



Photo 8: View of asbestos-containing vinyl floor tile (12"x12"-White with beige spots) observed to be in poor condition in Room C144.

This damage has been repaired.



Photo 9: View of non-asbestos containing fireproofing observed above the suspended ceiling tiles in Room C141C.



Photo 10: View of non-asbestos containing vinyl floor tiles (12"x12"-Pink with dots) and vinyl floor tiles (12"x12"-Offwhite with dots) observed in Room C115.



Photo 11: View of non-asbestos containing glued on acoustic tile (12"x12"-Uniform Holes) and adhesive mastic (brown) observed in the Men's Change Room in D108.



Photo 12: View of low-level lead paint observed to be in poor condition in Room A144.



Photo 13: View lead containing white paint observed to be in poor condition in Mechanical Room D201.




Photo 14: View of water damage on drywall observed in Room E117.



Photo 15: View of lead acid battery pack observed outside of D201.



Photo 16: View of diagnostic machine suspected to contain radioactive materials observed in Room E029.



Photo 17: Typical view of non-PCB containing light ballast observed throughout the surveyed building.



Photo 18: View of water-stained suspended ceiling tiles in Room A104C.

This damage has been repaired.

APPENDIX E

Asbestos-Containing Materials Checklists

Hazardous Materials Survey and 2023 Reassessment
200 Lees Avenue, Ottawa, Ontario
Appendix E - Asbestos Containing Materials Checklist

Z1920014HZ / CCC-230252-00

| Floor/Level | Location | Type of ACM | Asbestos Confirmed/ Suspected | Friable/Non-Friable | Damaged/ Deteriorated | Accessibility | Level of Work Near Material | Quantity # | Unit | Recommended Action | Comments |
|-------------|------------------|--|-------------------------------|---------------------|-----------------------|---------------|-----------------------------|------------|------|--|---|
| 0 | Room A02 | Mechanical Gasket Insulation | Confirmed | Friable | Poor Condition | Easy | Moderate | 1 | SF | Repair or Remove Following Type 1/2 Abatement Procedures | |
| 0 | Room E029 | Mechanical Pipe fittings/Elbows Insulation | Confirmed | Friable | Good Condition | Moderate | Moderate | ~4 | C | Manage in Place | |
| 0 | Throughout Level | Fire Doors | Suspected | Non-Friable | Good Condition | Easy | Low | N/A | N/A | Manage in Place | |
| 1 | Room A139 | Window Caulking (Black) | Confirmed | Non-Friable | Good Condition | Easy | Moderate | ~300 | LF | Manage in Place | |
| 1 | Room A105 | Mechanical Pipe Straight Insulation | Confirmed | Friable | Poor Condition | Easy | Moderate | 5 | LF | Remove Following Type 2 (Glovebag) Abatement Procedures | Observed in between workbenches at Cabinet 510. |
| 1 | Room A104C | Mechanical Pipe fittings/Elbows Insulation | Confirmed | Friable | Poor Condition | Easy | Moderate | 10 | C | Remove Following Type 2 (Glovebag) Abatement Procedures | |
| 1 | Room A138C | Transite | Suspected | Non-Friable | Good Condition | Difficult | Low | 1 | LF | Manage in Place | |
| 1 | Room A142 | Ceiling Plaster (Gray) | Confirmed | Friable | Good Condition | Difficult | Moderate | 100 | SF | Manage in Place | |
| 1 | Room C100D | Ceiling Plaster (Gray) | Confirmed | Friable | Good Condition | Moderate | Moderate | 100 | SF | Manage in Place | |
| 1 | Room C110 | Vinyl Floor Tiles (12"x12"-White with beige spots) | Confirmed | Non-Friable | Fair Condition | Easy | Low | ~20 | SF | Monitor Condition of Material. Consider Removal or Repair. | Elevator within B100 Hallway |
| 1 | Throughout Level | Fire Doors | Suspected | Non-Friable | Good Condition | Easy | Moderate | N/A | N/A | Manage in Place | |
| 2 | Room B215N | Wall Plaster (Gray) | Confirmed | Friable | Fair Condition | Moderate | Moderate | ~100 | SF | Monitor Condition of Material. Consider Removal or Repair. | |
| 2 | Throughout Level | Fire Doors | Suspected | - | Good Condition | Easy | Low | - | N/A | Manage in Place | |
| Roof | Throughout Level | Roofing Materials | Suspected | - | Good Condition | Easy | Low | - | N/A | Manage in Place | |

APPENDIX F


Hazardous Containing Materials Checklists

| Floor/Level | Location | Type | Component | Colour | Condition | Manufacturer | Quantity # | Unit | Suspected/ Confirmed | Recommended Action | Comments |
|-------------|--------------------|----------------------------------|---|--------|----------------|--------------------|------------|------|-------------------------|--|---|
| 0 | A02 | Lead | Battery Pack | N/A | Good Condition | Various | 2 | C | Confirmed | Manage In Place | |
| 0 | A02 | Lead | Battery Pack | N/A | Good Condition | LumaCell | 1 | C | Confirmed | Manage In Place | |
| 0 | A02 | Mercury | Pressure Gauges, Float Switch | N/A | Good Condition | Various | - | - | Confirmed | Manage In Place | |
| 0 | C02 | Mercury | Pressure Gauges, Float Switch | N/A | Good Condition | Various | - | - | Confirmed | Manage In Place | |
| 0 | E037 | Ozone Depleting Substances (ODS) | Refrigerator/Freezer/Mini-Fridge/Water Cooler | N/A | Good Condition | Frigidaire | 1 | C | Confirmed | Manage In Place | |
| 0 | Room E026 | Ozone Depleting Substances (ODS) | Refrigerator | N/A | Good Condition | Woods | 1 | C | Confirmed | Manage in Place | |
| 0 | Room E043 | Ozone Depleting Substances (ODS) | Refrigerator | N/A | Good Condition | Woods | 1 | C | Confirmed | Manage in Place | |
| 0 | E010 Hallway | Lead | Paint | White | Good Condition | N/A | - | - | Confirmed | Manage in Place | |
| 0 | Throughout Level | Mercury | Fluorescent Light Tubes | N/A | Good Condition | N/A | - | N/A | Confirmed | Manage in Place | |
| 0 | Room E029 | Lead | Drywall | N/A | Good Condition | N/A | - | - | Suspected | Manage in Place | Potential lead shielding in the vicinity of Room E029 |
| 0 | Room E029 | Radioactive Materials | Diagnostic Equipment | N/A | Good Condition | GE Medical Systems | 1 | C | Confirmed | Manage in Place | |
| 0 | Throughout Level | Silica | Concrete, Mortar, Etc. | N/A | Good Condition | N/A | - | - | Confirmed | Manage in Place | |
| 0 | Throughout Level | Lead | Battery Pack | N/A | Good Condition | N/A | - | - | Confirmed | Manage in Place | |
| 0 | Room E041 | Ozone Depleting Substances (ODS) | Air Conditioning Unit | N/A | Good Condition | Climate-Master | 1 | C | Confirmed | Manage in Place | |
| 0 | Room E042 | Ozone Depleting Substances (ODS) | Air Conditioning Unit | N/A | Good Condition | Keep-Rite | 1 | C | Confirmed | Manage in Place | |
| 0 | Room E043 | Ozone Depleting Substances (ODS) | Air Conditioning Unit | N/A | Good Condition | Norbec | 1 | C | Confirmed | Manage in Place | |
| 1 | A104 | Mould/ Water Damage | Ceiling Tiles | N/A | Fair Condition | - | 2 | C | Confirmed | Must be removed and disposed of as per EACO Guidelines. | |
| 1 | A105 | Lead | Battery Pack | N/A | Good Condition | LumaCell | 1 | C | Confirmed | Manage In Place | |
| 1 | A133 | Lead | Battery Pack | N/A | Good Condition | LumaCell | 1 | C | Confirmed | Manage In Place | |
| 1 | A140 | Lead | Paint | Beige | Poor Condition | N/A | 3 | SF | Confirmed | Paint must be removed and/or stabilized following Class 1/2 or Type 1/2 lead Safety Procedures as per EACO Guidelines. | |
| 1 | Room A139 | Lead | Paint | White | Good Condition | N/A | - | - | Confirmed | Manage in Place | |
| 1 | Room B157, Columns | Lead | Paint | White | Good Condition | N/A | - | - | Confirmed | Manage in Place | |
| 1 | Throughout Level | Lead | Paint | Beige | Good Condition | N/A | - | - | Confirmed | Manage in Place | |
| 1 | Room A129 | Ozone Depleting Substances (ODS) | Ice Making Machine | N/A | Good Condition | Manitowoc | 1 | C | Confirmed | Manage in Place | |
| 1 | Throughout Level | Mercury | Fluorescent Light Tubes | N/A | Good Condition | N/A | - | N/A | Confirmed | Manage in Place | |
| 1 | Throughout Level | Silica | Concrete, Mortar, Etc. | N/A | Good Condition | N/A | - | - | Confirmed | Manage in Place | |
| 1 | Room A129 | Ozone Depleting Substances (ODS) | Air Conditioning Unit | N/A | Good Condition | N/A | 1 | C | Confirmed | Manage in Place | |
| 1 | Room B153A | Ozone Depleting Substances (ODS) | Air Conditioning Unit | N/A | Good Condition | Mitsubishi | 1 | C | Confirmed | Manage in Place | |

| Floor/Level | Location | Type | Component | Colour | Condition | Manufacturer | Quantity # | Unit | Suspected/ Confirmed | Recommended Action | Comments |
|-------------|------------------|-------------------------------------|---|--------|----------------|-------------------|------------|------|-------------------------|--|----------|
| 1 | E103 | Ozone Depleting Substances (ODS) | Air Conditioning Unit | N/A | Good Condition | Friedrich | 1 | C | Confirmed | Manage in Place | |
| 2 | C200 | Ozone Depleting Substances (ODS) | Refrigerator/Freezer/Mini- Fridge/Water Cooler | N/A | Good Condition | Various | 1 | C | Confirmed | Manage in Place | |
| 2 | E255A | Ozone Depleting Substances (ODS) | Refrigerator | N/A | Good Condition | Thermo-Scientific | 3 | C | Confirmed | Manage in Place | |
| 2 | E250 | Lead | Battery Pack | White | Good Condition | N/A | 1 | c | Confirmed | Manage in Place | |
| 2 | Room B208B | Lead | Paint | White | Poor Condition | N/A | ~6 | SF | Confirmed | Paint must be removed and/or stabilized following Class 1/2 or Type 1/2 lead Procedures as per MOL and EACO Guidelines. | |
| 2 | Room D201 | Lead | Paint | White | Poor Condition | N/A | ~12 | SF | Confirmed | Paint must be removed and/or stabilized following Class 1/2 or Type 1/2 lead Procedures as per MOL and EACO Guidelines. | |
| 2 | Throughout Level | Lead | Paint | White | Good Condition | N/A | - | - | Confirmed | Manage in Place | |
| 2 | B208B | Lead | Paint | Green | Poor Condition | N/A | ~1 | SF | Confirmed | Paint must be removed and/or stabilized following Class 1/2 or Type 1/2 lead Procedures as per MOL and EACO Guidelines. | |
| 2 | E255 | Ozone Depleting Substances (ODS) | Ice Making Machine | N/A | Good Condition | Hoshizaki | 1 | C | Confirmed | Manage in Place | |
| 2 | Throughout Level | Mercury | Fluorescent Light Tubes | N/A | Good Condition | N/A | - | N/A | Confirmed | Manage in Place | |
| 2 | Throughout Level | Silica | Concrete, Mortar, Etc. | N/A | Good Condition | N/A | - | N/A | Confirmed | Manage in Place | |
| 2 | Throughout Level | Lead | Battery Pack | N/A | Good Condition | N/A | - | N/A | Confirmed | Manage in Place | |
| 2 | Throughout Level | Ozone Depleting Substances (ODS) | Ice Making Machine | N/A | Good Condition | Hoshizaki | 1 | C | Confirmed | Manage in Place | |
| 3 | E301 | Lead | Battery Pack | N/A | Good Condition | N/A | 1 | C | Confirmed | Manage In Place | |
| 3 | Throughout Level | Mercury | Fluorescent Light Tubes | N/A | Good Condition | N/A | - | N/A | Confirmed | Manage in Place | |
| 3 | Throughout Level | Silica | Concrete, Mortar, Etc. | N/A | Good Condition | N/A | - | N/A | Confirmed | Manage in Place | |
| 3 | Throughout Level | Lead | Battery Pack | N/A | Good Condition | Various | - | N/A | Confirmed | Manage in Place | |

APPENDIX G

Site Sampling & Location Plans



Legend:

- ▲ Asbestos Bulk Sample
- Lead Paint Sample

- ACM Vinyl floor Tile (VFT)
- ACM Pipe Insulation
- ACM Plaster
- ACM Window Caulking

| REV | DATE | DESCRIPTION | BY |
|-----|------|-------------|----|
| | | | |
| | | | |
| | | | |
| | | | |

McINTOSH PERRY
6240 HIGHWAY 7, SUITE 200
WOODBIDGE, ON., L4H 4G3
Tel: 905.856.5200 Fax: 905.695.0221
Toll Free: 1.888.348.8991
www.mcintoshperry.com



uOttawa
**Immeubles
Facilities**

200 LEES
200 LESS

200 LESS

| | | | |
|---|-------------------------|----------------|--------------|
| Dessin / Drawing: LEVEL 0 BUILDING COMBINATION | | | |
| Édifice/Bldg ---- 060 ---- | Niveau/Level: 0 ---- | Feuille/Sheet: | |
| Echelle/Scale: 1:600 | Revision: 1 | 08/09/2015 | A-0 of/de |

JB BUILDING COMBINED



- Legend:**
- ▲ Asbestos Bulk Sample
 - Lead Paint Sample
 - ACM Vinyl floor Tile (VFT)
 - ACM Pipe Insulation
 - ACM Plaster
 - ACM Window Caulking

| REV | DATE | DESCRIPTION | BY |
|-----|------|-------------|----|
| | | | |
| | | | |
| | | | |

McINTOSH PERRY
6240 HIGHWAY 7, SUITE 200
WOODBRIDGE, ON., L4H 4G3
Tel: 905.856.5200 Fax: 905.695.0221
Toll Free: 1.888.348.8991
www.mcintoshperry.com



uOttawa
Immeubles
Facilities


200 LEES
200 LESS

200 LESS

Dessin / Drawing: **LEVEL I**
BUILDING COMBINATION

| | |
|-------------------------------|--------------------------------|
| Édifice/Bldg ---- 060 ---- | Niveau/Level: 0 ---- |
| Échelle/Scale: 1:600 | Feuille/Sheet: A-I of/de |

JB BUILDING COMBINED



Legend:

▲ Asbestos Bulk Sample

■ Lead Paint Sample

ACM Vinyl floor Tile (VFT)

ACM Pipe Insulation

ACM Plaster

ACM Window Caulking

| REV | DATE | DESCRIPTION | BY |
|-----|------|-------------|----|
| | | | |
| | | | |
| | | | |

McINTOSH PERRY

6240 HIGHWAY 7, SUITE 200
WOODBRIDGE, ON., L4H 4G3
Tel: 905.856.5200 Fax: 905.695.0221
Toll Free: 1.888.348.8991
www.mcintoshperry.com



uOttawa

Immeubles
Facilities


200 LEES
200 LESS

200 LESS

Dessin / Drawing: **LEVEL 2**
BUILDING COMBINATION


| | |
|-------------------------------|--------------------------------|
| Édifice/Bldg ---- 060 ---- | Niveau/Level: 0 ---- |
| Échelle/Scale: 1:600 | Feuille/Sheet: A-2 of/de |

JB BUILDING COMBINED



| REV | DATE | DESCRIPTION | B |
|-----|------|-------------|---|
| | | | |
| | | | |
| | | | |
| | | | |

| |
|---|
| <p>McINTOSH PERRY</p> <p>6240 HIGHWAY 7, SUITE 200 WOODBIDGE, ON., L4H 4G3</p> <p>Tel: 905.856.5200 Fax: 905.695.0222 Toll Free: 1.888.348.8991</p> <p>www.mcintoshperry.com</p> |
|---|

| |
|--|
|  <p>uOttawa</p> <p>Immeubles Facilities</p> |
|--|

| |
|---|
| <p>200 LEES</p> <p>200 LESS</p> <p>----</p> <p>200 LESS</p> <p>----</p> |
|---|

| | | | |
|---|-----------------------|---|--|
| Dessin / Drawing: LEVEL 3 BUILDING COMBINATION ---- | | | |
| Édifice/Bldg ---- 060 ---- | | Niveau/Level: 0 ---- | |
| ---- ---- ---- | | Feuille/Sheet: | |
| Échelle/Scale: 1:600 | Revision: 1 | <div style="display: flex; justify-content: space-between;"> <div>08/09/2015</div> <div>A-3</div> </div> <div style="text-align: right;">of/de</div> | |